

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

	<u>Marquette</u> <small>(County)</small>	Located In:	Corner Code #
1. Public Land Survey		T <u>45N</u> R <u>25W</u>	<u>B-10, B-9, C-10</u>
		T _____ R _____	_____
		T _____ R _____	_____
		T _____ R _____	_____
2. Property Controlling in Section	S _____	T _____ R _____	_____
	S _____	T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____	T _____ R _____	_____
	S _____	T _____ R _____	_____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, David B. Babbitt, in a field survey on 10/13/88, 19____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- B-10. C 1/4 corner of Section 30. 3/4" iron pin, Marquette Co. Road Commission. 6" spruce, S68W, 22.05'; 5" j.pine, N53W, 15.95'
- B-9. N 1/4 corner of Section 30. Wood post, 1852. Hemlock 6, N31W, 13 Lks. Maple 6, S80E, 15 Lks.
- C-10. E 1/4 corner of Section 30. Hemlock post, 1852. y.pine 14", S70W, 30 Lks. B. oak, 24", N26E, 45 Lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- B-10. Set at the intersection of the N-S and E-W 1/4 lines of Section 30. Found iron and Co. Rd. Comm. NBTs but found no record and no monument for either the N 1/4 corner or the East 1/4 so must conclude Co. Rd. Comm. iron was not set by proper section sub'n. methods. Co. Rd. Comm. iron is S53W, 15.8' from this corner monument.
- B-9. Set by single proportion to the original survey record between the NW and NE section corners of Section 30. Could not identify OBTs.
- C-10. Set MPOL between the NE and SE section corners of Section 30. Could not identify OBTs.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | | |
|--|---|--|
| B-10. DNR Monument.
6" w.pine, N6W, 20.5'
10" j.pine, N86W, 24.55'
6" w.pine, S45W, 32.5'
8" j.pine, S33E, 12.6' | B-9. DNR Monument.
20" w.pine, N61E, 31.3'
8" maple, S51E, 5.95'
9" spruce, S79W, 20.1'
7" maple, N41W, 13.7' | C-10. DNR Monument.
6" w.pine, N69E, 19.85'
4" w.pine, S37E, 14.85'
5" w.pine, N75W, 40.0'
6" r.maple, N19W, 32.1' |
|--|---|--|

Signed by David B. Babbitt Date 1-26-89
 Surveyor's Michigan License No. 21558