

**SURVEY &  
REMONUMENTATION**

MAR 13 1998

SECTION

**LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970**

MARQUETTE COUNTY  
MICHIGAN  
RECEIVED FOR RECORD

1997 DEC 26 PM 12: 47

*Patricia A. Monbey*  
REGISTER OF DEEDS

For corners in

MARQUETTE  
(County)

Located In:

Corner Code #

- |                                       |         |                           |            |
|---------------------------------------|---------|---------------------------|------------|
| 1. Public Land Survey                 |         | T <u>46N</u> R <u>25W</u> | <u>K-5</u> |
|                                       |         | T _____ R _____           | _____      |
|                                       |         | T _____ R _____           | _____      |
|                                       |         | T _____ R _____           | _____      |
| 2. Property Controlling<br>in Section | S _____ | T _____ R _____           | _____      |
|                                       | S _____ | T _____ R _____           | _____      |
| 3. Miscellaneous<br>Property in Sec.  | S _____ | T _____ R _____           | _____      |
|                                       | S _____ | T _____ R _____           | _____      |

LIBER **2** PAGE **40**  
Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, GERALD W. CARLSON, in a field survey on JUNE 28TH, 19 97, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

**A. Description of original monument and accessories and/or subsequent restoration:**

K-5: Section Corner common to Sections 11, 12, 13, and 14.  
1845: William Ives' original subdivision survey notes describe the corner monument as a wood post referenced by:  
20" Sugar N46E, 23 L 8" Y. Birch S20W, 27 L

No Date: The M.C.R.C. Government Corner Index Book (F.B. #647 - Sec. 14) indicates that the corner was established for the Plat of Sawyer Glenn. No description of corner object or accessories given.

1973: The corner is shown on the Plat of Swayer Glen, surveyed by William R. Donnan P.S. #17618, and recorded in L. 87, Plats Pg. 295. Distance S89°09'35"W, 2610.35' to the North 1/4 Corner of Section 14. No description of corner object or accessories given.

1973/80: An LCRC recorded in 1980 by William R. Donnan P.S. #17618 in L. 4, RC Pg. 31, and based on a survey in 1973, indicates the corner as a found 1 1/2" diam. Iron Rod 1' N. of the Center of Co. Rd. 553, on line with a fence to the South. Referenced by:  
7" Apple S46E, 38.66' 4" Wild Cherry S37W, 64.66'  
5" Apple Cluster N69W, 60.45'

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

K-5: 1997: No original corner evidence found. Found and accepted a 1-1/2" diam. Steel Rod 1.7' long in asphalt bent Easterly, slightly above grade and located 1.3' North of C/L of Taylor Rd. (Co. Rd. NT). An existing fence line coursing North, then Easterly, was found 36' North of Steel Rod. Found existing references as described in Part C below. There were no nearby line calls to check. Distance West is 2632.87', distance South is 2628.01' and distance East is 2656.79'.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

K-5: 1997: Replaced found Steel Rod with a 3/4" diameter x 36" long Rebar capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner. New monument was set at the straightened part of found Steel Rod. A monument box set in 6" deep concrete was placed around new monument. Monument is 7" below asphalt surface located 1.3' North of C/L Taylor Rd. (Co. Rd. NT). Measured found references:  
10" Apple S40E, 38.3' (Donnan NBT)  
6"-7" Apple Cluster N64W, 60.45' (Donnan NBT)  
Established new references:  
5" Apple S42E, 38.21' (to set d.h. nail) (Donnan NBT)  
6" Apple N69W, 60.19' (to set d.h. nail) (Donnan NBT)  
7" R. Pine N14E, 50.13' (to set d.h. nail)  
12" Twin Poplar N48W, 27.16' (to set d.h. nail) (Ornamental tree - B.T. Tag only - No Blazes)  
Green Steel Sign Post w/ Yellow Survey Marker Sign, S12W, 26.3'  
Note: Unless otherwise noted, bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.  
Bk. 9, Pg. 125

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

RATIFIED BY PEER GROUP  
P.A. 345 OF 1990

*Larry J. Buasme*  
DATE 12/8/97

Signed by Gerald W. Carlson

Date 12-18-97

Surveyor's Michigan License No. 24589

