

SURVEY & REMONUMENTATION

#912

DEC 27 1993

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 283 PAGE 438

COMMISSION

For corners in

<u>Missaukee</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>21N</u> R <u>7W</u>	<u>K-13</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

MISSAUKEE COUNTY MICHIGAN

RECORDED **DEC 16 1993** 12:40 PM

Paulyn Flare
REGISTER

Register of Deeds Stamp & File Number

I, J. Dean Geers, in a field survey on December 15, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	N
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- K-13) 1837 GLO Section post by John Brink, Deputy Surveyor
Hemlock 16 N 30° E 31, Maple 10 N 51 1/2° W 35
- K-13) 1893 Beuthien survey in Section 36: Stone, Iron, Crockery
- K-13) 1993 Granger survey in Section 35, Liber S-3, pages 181-182: Set 1/2" Iron and cap

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- K-13) Section corner common to Sections 35 and 36
Found Granger Iron of record per Liber S-3, pages 181-182 but it was not utilized in this survey.
Reestablished the Section corner common to Sections 35 and 36 based on a retracement of the 1893 Beuthien survey of Section 36. No physical evidence of the corner was found so the corner position was determined by prorating the recorded Beuthien distances which were consistant throughout the section. This corner is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- K-13) Set 1/2" x 36" Iron and Missaukee County monument
Corner falls ±12' West of the centerline of North-South field lane, ±24' North of centerline of East-West field lane.
N 71° E - 29.87 - 20" Dogwood
S 75° E - 44.47 - Corner fence post
S 69° E - 28.46 - 12" Dogwood
S 20° E - 35.93 - 14" Dogwood
S 39° W - 65.22 - 10" Poplar
S 15° E - 73.59 - Granger Iron

Peer Group Reviewed and Approved
Date: 12-15-93
J. Dean Geers
J. Dean Geers, Missaukee Co. Representative

Signed by *J. Dean Geers* Date 12/15/93

Surveyor's Michigan License No. 33977