

SURVEY & REMONUMENTATION

APR 24 1995

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
 MONTMORENCY COUNTY
 Recorded & Filed

For corners **COMMISSION**

11-10-1994 14:14:16

A. PANGAN-MCELROY
 REGISTER OF DEEDS

Register of Deeds Stamp & File Number

Montmorency (County) Located in: Montmorency Township Corner Code # A-5

1. Public Land Survey T 32 N R 3 E A-5
 T ___ R ___
 T ___ R APPROVED BY
 T ___ R PEER GROUP

2. Property Controlling in Section S ___ T ___ R ___
 S ___ T ___ R AUG 0 5 94

3. Miscellaneous Property in Sec. S ___ T ___ R ___
 S ___ T ___ R [Signature]

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

I, Don Marlatt in a field survey on November 8, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(A-5) S.W. Cor. Sec. 7, T 32 N, R 3 E
 Original post set by Hiram Burnham July, 1850.
 10" Cedar N 60° W 20 links
 6" Cedar S 20° W 15 links
 Schaaf - DNR Survey - No Date.
 D. Porter - Recorded Act 74, L. 1, P. 397 on July 22, 1987.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A-5) S.W. Cor. Sec. 7, T 32 N, R 3 E
 Found 2" pipe in concrete & 4" x 4" stake - 20'± East of trail.
 10" Cedar N 28° W 8.27'
 8" Cedar N 77° E 9.7'
 8" Cedar S 11° E 2.5'
 12" Cedar S 82° W 15.8'
 No evidence of original corner.

Accepted as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A-5) S.W. Cor. Sec. 7, T 32 N, R 3 E
 Left 2" pipe & concrete in place.
 Placed Remonumentation Cap.
 10" Cedar N 28° W 8.07'
 12" Cedar S 82° W 15.55'
 8" Cedar S 11° E 2.17'
 8" Cedar N 77° E 9.70'

Witnesses marked with a 30 penny spike & I.D. tag #18660.



Signed by Donald E Marlatt

Date 11-9-1994

Surveyor's Michigan License No. 18660