

**SURVEY &  
REMONUMENTATION**

LIBER 15234 PG 548

295019995

MAY - 1 1995

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

**COMMISSION**

<u>Oakland</u> (County)	Located in: Addison Township	Corner Code # <u>L-11</u>
1. Public Land Survey	T <u>5N</u> R <u>11E</u>	<u>L-11</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

\$ 7.00 MISCELLANEOUS RECORDING  
\$ 2.00 REMONUMENTATION  
2 FEB 95 7:25 A.M. RECEIPT# 28  
PAID RECORDED - OAKLAND COUNTY  
LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

**OK - T. SMITH**

Compliance with  
ACT 345, P.A. 1990

APPROVED ON: 12-12-94  
OAKLAND COUNTY REMONUMENTATION  
PEER GROUP COMMITTEE  
Register of Deeds Stamp & File Number

I, Randy Kolehouse, in a field survey on July 18 19 94, do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

L-11 Per G.L.O. notes, J. Wampler set a post in 1817.

Oakland Co. Road Comm. 1933  
1" Iron  
NNE 19.85' Stone Pillar  
SSE 34.85' Nail in 10" Blk. Oak

L.C.R.C. L. 7448 P. 116 1979  
1/2" Iron  
North 26.30' to SW Cor. Conc. Slab at Fence Cor.  
S 40° E 28.48' Nail & Flasher 42" Oak  
S 10° W 41.60' Nail & Flasher in Util. Pole

Kobs Survey 1991  
1/2" Iron Bar  
SE 29.82' P.K. in 42" Oak  
SSW 42.17' P.K. in P. Pole  
NNE 25.83' SE Cor. Conc. Cap on  
Stone Pillar

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L-11 Found 1/2" iron bar 3' M/L North of the C/L of Brewer Road (gravel) running E-W. Checked the following witnesses.

L.C.R.C. L. 7448 P. 116 1979  
North 25.95' SW Cor. Conc. Slab on Fence Post (Stone)  
S 40° E 28.83' Nail & Flasher N Side 42" Oak  
S 10° W 41.88' Nail & Flasher W Side P. Pole

Kobs Measures West 2641.86' to K-11  
Kobs Measures North 2560.84' to L-10

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-11 Set a 5/8" rebar with brass cap stamped "Oakland County Remonumentation P.S. #25854" in place of found 1/2" iron rod.

PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in S Side 12" Oak N 57° W 42.86'  
NW Cor. Hse. Fndn. Hse. #1505 N 37° E 149.90'  
SW Cor. Conc. Slab on Stone Fence Post North 25.95'  
PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in N Side 42" Oak S 40° E 28.83'  
PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in W Side P. Pole S 10° W 41.88'

The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Signed by Randy J. Kolehouse  
Surveyor's Michigan License No. 25854

Date 12/23/94

