

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 51N R 37W	F5
	T _____ R _____	(GCDB 340500)
	T _____ R _____	
2. Property Controlling in Section	S 15 T 51N R 37W	3
	S _____ T _____ R _____	(GCDB 400460)
	S _____ T _____ R _____	
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	
	S _____ T _____ R _____	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Stephan J. Szyszkoski, in a field survey on 08/18/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F5) Quarter corner common to Sections 9 and 16. In 1976, K.L.Sackett RLS reestablished the position for the corner midway and on line between Section corners. Set 1"IDx36" I.pipe with 4" alum. cap. 8" Y.Birch S14°E 26.8', 10" Basswood N62°W 15.7'.

(3-Sec. 15) North 1/16 corner between Sections 15 and 16. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F5) Found the 1976 monument in good condition and at record bearing and distance from the 1976 NBTs. The Y.Birch is a dead stub, the NBT NW, noted as a Basswood, is actually an Ash, in good condition with double over-grown blazes. The monument is substantially at the position of record and I accept same as a careful and faithful reestablishment of the position of the original corner.

(3-Sec. 15) Established the position for the corner on a straight line between Section corner 1360.89' north and Quarter corner 1360.89' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F5) Found 1"ID I.pipe with 4" brass MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:
 12" W.Ash N58°W 16.1' old blazes (1976 NBT)
 6" squared Sugar S66°E 2.6' (1976 marker tree)
 9" Sugar S48°E 8.35' mrkd "1/4S NBT"
 7" Sugar S06°W 18.25' do
 5" Sugar N21°W 2.8' do
 E= 7846970.172 N= 228566.853

(3) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
 8" Sugar S85°E 30.05' mrkd "1/16S BT"
 4" Sugar S10°E 2.75' do
 5" Iron N71°W 2.15' do
 6" Sugar N11°W 18.1' do
 Sq'd a 3" Ironwood S32°W 2.3' for a post.
 E= 7847761.209 N= 228156.603

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum
 Coord. Ref.=NGS PID RL0593: N= 221669.506 m. E= 7868965.488 m.

Signed by Stephan J. Szyszkoski
 Surveyor's Michigan License No. 33986

Date 08/26/2015

For the Michigan Department of Natural Resources, Forest Resources Division

