

SCHOOLCRAFT COUNTY  
PEER GROUP APPROVED

DATE 10/15/97

SURVEY &  
REMONUMENTATION

JAN 21 1998

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T42NR16W	H-7
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

SECTION

Received & Filed this 9 day of  
Dec. 1997 at 4:01 P.M.  
Sigrid I. Hedberg  
Schoolcraft Co. Reg. of Deeds

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Thomas P. O'Brien in a field survey on Nov. 4, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7								X					
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

H-7 N 1/4 Corner Section 22  
Aug. 14, 1850 - Algernon Merryweather D.S. set qr. section post.  
Beech 8 S27W 20 lks. do. 4 N30E 7 lks.  
  
Feb. 7, 1977 - Beryl M. Jones R.L.S. found iron bar. LCRC recorded  
Liber 1, page 236.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-7 Nov. 4, 1997 - Thomas P. O'Brien P.S. recovered 1/2" iron bar in black top. Witness verifies corner location. Reset iron bar with 1/2" I.B. and O'Brien cap #21274 in monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-7 1/2" I.B. w/O'Brien cap #21274 in monument box.

Witnesses: (Fd.) 10" Beech - S30°E - 25.85'  
NBT. 10" Maple - S31°W - 32.05'  
NBT. 8" Maple - N33°W - 67.14'  
NBT. 10" Maple - N55°E - 35.70'  
4" Cedar Post - North - 30.0'



Signed by Thomas P. O'Brien P.S.

Date November 26, 1997

Surveyor's Michigan License No. 21274