Hereld Carlyn LAND CORNER RECORDATION CER	TIFICATE 5-2/
Chairman Filing Requirement of Act 74, Mich. I	P.A. 1970
For corners in ALGER Located In: Corner Code #	איין ויין
(County)	FILED
	TIME 2:00 pm.
1. Public Land Survey T 45N R 21W F1	1417 7 4 447
T 46NR 21W F13	MAR 3 1 1997
T R	DONALD W. KINNUNEN
2. Property Controlling S T R	REGISTER OF DEEDS
in Section S T R	ALGER COUNTY, MI
3. Miscellaneous S T R	Register of Deeds Stamp & File Number
Froperty in Section 5 1 n	
4. Lot No, Recorded Plat	TAGN. B.ZIW FIZ A B C D E E G H I J K L N
5. Private Claims	
•	4 7 8 9 10 11 12
I, Robert L. Jamros , in a field survey on August 29, 1996 , 19	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points me	entioned 6 18 17 16 15 14 13
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the manual of survey instructions of the United States Department of the Interior, Bureau	7
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines	3, 4 and 8 19 20 21 22 23 24
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors Decree of a Court of Law; established, re-established, monumented, re-monumented, recovere	
as expressed below:	10 29 28 27 26 25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	11
on this certificate.	12 31 32 33 34 35 36
64.44 feet. * Stop sign, N.22 W., 56.77 feet. * S.E. corner of 18° x 22° conc. sl. Alger County Records. ***** Robert L, Jamros, RLS, 1990. * Alger County Road Comm. from Eben-Trenary Road East two miles to the intersection of State Highways M-94 corner position recovered during the centerline alignment and greliminary survey.	ission Project for the rehabilitation of Tunteri Road and M-67. * Existing 5/8" rebar monument at this
Alger County Records. ***** Robert L, Jamros, RLS, 1990. * Alger County Road Comm.	ission Project for the rehabilitation of Tunteri Road and M-67. * Existing 5/8" rebar monument at this
Alger County Records. ***** Robert L, Jamros, RLS, 1990. * Alger County Road Comm from Eben-Trenary Road East two miles to the intersection of State Highways M-94 corner position recovered during the centerline alignment and preliminary survey were supported to the content of	ission Project for the rehabilitation of Tunteri Road and M-67. * Existing 5/8" rebar monument at this work for this project. Corner position documented on establishing corner: In 1990 centerline alignment plans of the Tunteri Road, of centerline of gravel road to South and 9.0 feet and established references. Monumented corner
Alger County Records. ***** Robert L, Jamros, RLS, 1990. * Alger County Road Comm. from Eben-Trenary Road East two miles to the intersection of State Highways M-94 corner position recovered during the centerline alignment and preliminary survey construction plans of Tunteri Road, Alger County. * Not recorded. B. Description of corner evidence found and/or method applied in restoring or ree fi: Established corner position by standard survey methods and references based or Corner position lies 0.80 feet North of centerline of Tunteri Road, 8.0 feet East East of centerline of gravel road to North. Installed monument at corner position position was established from the best available evidence and is accepted as a car	ission Project for the rehabilitation of Tunteri Road and M-67. * Existing 5/8" rebar monument at this work for this project. Corner position documented on establishing corner: In 1990 centerline alignment plans of the Tunteri Road, of centerline of gravel road to South and 9.0 feet and established references. Monumented corner
Alger County Records. ***** Robert L, Jamros, RLS, 1990. * Alger County Road Comm. from Eben-Trenary Road East two miles to the intersection of State Highways M-94 corner position recovered during the centerline alignment and preliminary survey construction plans of Tunteri Road, Alger County. * Not recorded. B. Description of corner evidence found and/or method applied in restoring or ree fi: Established corner position by standard survey methods and references based or Corner position lies 0.80 feet North of centerline of Tunteri Road, 8.0 feet East East of centerline of gravel road to North. Installed monument at corner position position was established from the best available evidence and is accepted as a car	ission Project for the rehabilitation of Tunteri Road and M-67. * Existing 5/8" rebar monument at this work for this project. Corner position documented on establishing corner: In 1990 centerline alignment plans of the Tunteri Road, of centerline of gravel road to South and 9.0 feet and established references. Monumented corner
Alger County Records. ***** Robert L, Jamros, RLS, 1990. * Alger County Road Comm. from Eben-Trenary Road East two miles to the intersection of State Highways M-94 corner position recovered during the centerline alignment and preliminary survey construction plans of Tunteri Road, Alger County. * Not recorded. B. Description of corner evidence found and/or method applied in restoring or ree fi: Established corner position by standard survey methods and references based or Corner position lies 0.80 feet North of centerline of Tunteri Road, 8.0 feet East East of centerline of gravel road to North. Installed monument at corner position position was established from the best available evidence and is accepted as a car	ission Project for the rehabilitation of Tunteri Road and M-67. * Existing 5/8" rebar monument at this work for this project. Corner position documented on establishing corner: In 1990 centerline alignment plans of the Tunteri Road, of centerline of gravel road to South and 9.0 feet and established references. Monumented corner
Alger County Records. ***** Robert L, Jamros, RLS, 1990. * Alger County Road Comm. from Eben-Trenary Road East two miles to the intersection of State Highways M-94 corner position recovered during the centerline alignment and preliminary survey construction plans of Tunteri Road, Alger County. * Not recorded. B. Description of corner evidence found and/or method applied in restoring or ree fi: Established corner position by standard survey methods and references based or Corner position lies 0.80 feet North of centerline of Tunteri Road, 8.0 feet East East of centerline of gravel road to North. Installed monument at corner position position was established from the best available evidence and is accepted as a car	ission Project for the rehabilitation of Tunteri Road and M-67. * Existing 5/8" rebar monument at this work for this project. Corner position documented on establishing corner: In 1990 centerline alignment plans of the Tunteri Road, of centerline of gravel road to South and 9.0 feet and established references. Monumented corner
Alger County Records. ***** Robert L, Jamros, RLS, 1990. * Alger County Road Comm. from Eben-Trenary Road East two miles to the intersection of State Highways M-94 corner position recovered during the centerline alignment and preliminary survey construction plans of Tunteri Road, Alger County. * Not recorded. B. Description of corner evidence found and/or method applied in restoring or ree fi: Established corner position by standard survey methods and references based or Corner position lies 0.80 feet North of centerline of Tunteri Road, 8.0 feet East East of centerline of gravel road to North. Installed monument at corner position position was established from the best available evidence and is accepted as a car	ission Project for the rehabilitation of Tunteri Road and M-67. * Existing 5/8" rebar monument at this work for this project. Corner position documented on establishing corner: In 1990 centerline alignment plans of the Tunteri Road, of centerline of gravel road to South and 9.0 feet and established references. Monumented corner
Alger County Records. ***** Robert L, Jamros, RLS, 1990. * Alger County Road Comm. from Eben-Trenary Road East two miles to the intersection of State Highways M-94 corner position recovered during the centerline alignment and preliminary survey construction plans of Tunteri Road, Alger County. * Not recorded. B. Description of corner evidence found and/or method applied in restoring or ree fi: Established corner position by standard survey methods and references based or Corner position lies 0.80 feet North of centerline of Tunteri Road, 8.0 feet East East of centerline of gravel road to North. Installed monument at corner position position was established from the best available evidence and is accepted as a car	ission Project for the rehabilitation of Tunteri Road and M-67. * Existing 5/8" rebar monument at this work for this project. Corner position documented on establishing corner: In 1990 centerline alignment plans of the Tunteri Road, of centerline of gravel road to South and 9.0 feet and established references. Monumented corner
Alger County Records. ***** Robert L, Jamros, RLS, 1990. * Alger County Road Comm. from Eben-Trenary Road East two miles to the intersection of State Highways M-94 corner position recovered during the centerline alignment and preliminary survey a construction plans of Tunteri Road, Alger County. * Not recorded. B. Description of corner evidence found and/or method applied in restoring or ree f1: Established corner position by standard survey methods and references based or Corner position lies 0.80 feet North of centerline of Tunteri Road, 8.0 feet East East of centerline of gravel road to North. Installed monument at corner position position was established from the best available evidence and is accepted as a can the orignal corner.	ission Project for the rehabilitation of Tunteri Road and M-67. * Existing 5/8° rebar monument at this work for this project. Corner position documented on establishing corner: In 1990 centerline alignment plans of the Tunteri Road, of centerline of gravel road to South and 9.0 feet in and established references. Monumented corner reful and faithful reestablishment of the position of
Alger County Records. ***** Robert L, Jamros, RLS, 1990. * Alger County Road Comm. from Eben-Trenary Road East two miles to the intersection of State Highways M-94 corner position recovered during the centerline alignment and preliminary survey we construction plans of Tunteri Road, Alger County. * Not recorded. B. Description of corner evidence found and/or method applied in restoring or recovered for the state of t	ission Project for the rehabilitation of Tunteri Road and M-67. * Existing 5/8" rebar monument at this work for this project. Corner position documented on establishing corner: In 1990 centerline alignment plans of the Tunteri Road, of centerline of gravel road to South and 9.0 feet in and established references. Monumented corner reful and faithful reestablishment of the position of the corner reful and faithful reestablishment of the position of the corner reful and faithful reestablishment of the position of the corner.
Alger County Records. ***** Robert L, Jamros, RLS, 1990. * Alger County Road Comm. from Eben-Trenary Road East two miles to the intersection of State Highways M-94 corner position recovered during the centerline alignment and preliminary survey we construction plans of Tunteri Road, Alger County. * Not recorded. B. Description of corner evidence found and/or method applied in restoring or recovered for the state of t	ission Project for the rehabilitation of Tunteri Road and M-67. * Existing 5/8" rebar monument at this work for this project. Corner position documented on establishing corner: In 1990 centerline alignment plans of the Tunteri Road, of centerline of gravel road to South and 9.0 feet in and established references. Monumented corner reful and faithful reestablishment of the position of the corner reful and faithful reestablishment of the position of the corner reful and faithful reestablishment of the position of the corner.
Alger County Records. ***** Robert L, Jamros, RLS, 1990. * Alger County Road Comm. from Eben-Trenary Road East two miles to the intersection of State Highways M-94 corner position recovered during the centerline alignment and preliminary survey we construction plans of Tunteri Road, Alger County. * Not recorded. B. Description of corner evidence found and/or method applied in restoring or recovered for the state of t	ission Project for the rehabilitation of Tunteri Road and M-67. * Existing 5/8" rebar monument at this work for this project. Corner position documented on establishing corner: In 1990 centerline alignment plans of the Tunteri Road, of centerline of gravel road to South and 9.0 feet in and established references. Monumented corner reful and faithful reestablishment of the position of the corner reful and faithful reestablishment of the position of the corner reful and faithful reestablishment of the position of the corner.
Alger County Records. ***** Robert L, Jamros, RLS, 1990. * Alger County Road Comm. from Eben-Trenary Road East two miles to the intersection of State Highways M-94 corner position recovered during the centerline alignment and preliminary survey we construction plans of Tunteri Road, Alger County. * Not recorded. B. Description of corner evidence found and/or method applied in restoring or recovered for the state of t	ission Project for the rehabilitation of Tunteri Road and M-67. * Existing 5/8" rebar monument at this work for this project. Corner position documented on establishing corner: In 1990 centerline alignment plans of the Tunteri Road, of centerline of gravel road to South and 9.0 feet in and established references. Monumented corner reful and faithful reestablishment of the position of the corner reful and faithful reestablishment of the position of the corner reful and faithful reestablishment of the position of the corner.
Alger County Records. ***** Robert L, Jamros, RLS, 1990. * Alger County Road Comm. from Eben-Trenary Road East two miles to the intersection of State Highways M-94 corner position recovered during the centerline alignment and preliminary survey construction plans of Tunteri Road, Alger County. * Not recorded. B. Description of corner evidence found and/or method applied in restoring or recovered former position by standard survey methods and references based on Corner position lies 0.80 feet North of centerline of Tunteri Road, 8.0 feet East East of centerline of gravel road to North. Installed monument at corner position position was established from the best available evidence and is accepted as a car	ission Project for the rehabilitation of Tunteri Road and M-67. * Existing 5/8" rebar monument at this work for this project. Corner position documented on establishing corner: In 1990 centerline alignment plans of the Tunteri Road, of centerline of gravel road to South and 9.0 feet in and established references. Monumented corner reful and faithful reestablishment of the position of the corner reful and faithful reestablishment of the position of the corner reful and faithful reestablishment of the position of the corner.
Alger County Records. ***** Robert L, Jamros, RLS, 1990. * Alger County Road Comm. from Eben-Trenary Road East two miles to the intersection of State Highways M-94 corner position recovered during the centerline alignment and preliminary survey we construction plans of Tunteri Road, Alger County. * Not recorded. B. Description of corner evidence found and/or method applied in restoring or reconstruction plans of Tunteri Road, Alger County. * Not recorded. B. Description of corner evidence found and/or method applied in restoring or reconstruction position by standard survey methods and references based or Corner position lies 0.80 feet North of centerline of Tunteri Road, 8.0 feet East East of centerline of gravel road to North. Installed monument at corner position position was established from the best available evidence and is accepted as a care the original corner. C. Description of monument for comer and accessories established to perpetuate file Set 5/8" x 18" Rebar with a 3 1/4" Aluminum cap no. RBD5325, stamped to identite PK nail with Aluminum I.D. washer. * Base of 6 foot steel post with "Survey Mar steel post with "Survey Mar ker" sign, 5.28 E., 46.84 feet. * Base of 6 foot steel post with "Survey Mar ker" sign, 5.28 E., 46.84 feet. * Base of 6 foot steel post with "Survey Mar ker" sign, 5.28 E., 46.84 feet. * Base of 6 foot steel post with "Survey Mar ker" sign, 5.28 E., 46.84 feet. * Base of 6 foot steel post with "Survey Mar ker" sign, 5.28 E., 46.84 feet. * Base of 6 foot steel post with "Survey Mar ker" sign, 5.28 E., 46.84 feet. * Base of 6 foot steel post with "Survey Mar ker" sign, 5.28 E., 46.84 feet. * Base of 6 foot steel post with "Survey Mar ker" sign, 5.28 E., 46.84 feet. * Base of 6 foot steel post with "Survey Mar ker" sign, 5.28 E., 46.84 feet. * Base of 6 foot steel post with "Survey Mar ker" sign, 5.28 E., 46.84 feet. * Base of 6 foot steel post with "Survey Mar ker" sign, 5.28 E., 46.84 feet. * Base of 6 foot steel post with "Survey Mar ker" sign, 5.28 E., 46.84 feet. * Base of	ission Project for the rehabilitation of Tunteri Road and M-67. * Existing 5/8" rebar monument at this work for this project. Corner position documented on establishing corner: In 1990 centerline alignment plans of the Tunteri Road, of centerline of gravel road to South and 9.0 feet in and established references. Monumented corner reful and faithful reestablishment of the position of the corner reful and faithful reestablishment of the position of the corner reful and faithful reestablishment of the position of the corner.

No. 25349

Signed by

Surveyor's Michigan License No.

PROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1963