## SURVEY & **EMONUMENTATION**

## JAN 1 8 2001

or corners in	SECT	ION
---------------	------	-----

American by Algor County

For corners in	LAND CORNE	R RECORDATION CERTIF	
POI COITIGIS III	Filing Require	ement of Act 74, Mich. P.A.	
Alger	Located In:	Corner Code #	05-226
(County)	-		FILED
1. Public Land Survey	T 46N R 17W	ł ·	TIME 850 Am.
	T R T R T R		DEC 20 2000
Property Controlling     in Section	S T R S T R		DONALD W. KINNUNEN REGISTER OF DEEDS ALGER COUNTY, MI
Miscellaneous     Property in Section	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No, Rec			A B C D E F G H I J K L M
5. Private Claims			2 6 5 3
Robert L. Jamros	August	22 2000	<u> </u>
do hereby state that under require in lines 1 and 2 above were in con	ements of P.A. 74, Michigan P. formance with regulations and	A. of 1970, the corner points menti rules therefore as required in the cu ment of the Interior, Bureau of	urrent
Management or by a decree of a 5 above were in conformance win Decree of a Court of Law; established.	Court of Law and/or that the c th the rules of the Michigan E	orner points mentioned in lines 3, 4 loard of Land Surveyors or	4 and 8 19 20 21 22 23 24 - r by a 9
as expressed below:  NOTE: Not more than 2 corne	ers, all in the same town an	d range, may be recorded	11 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

Elm 22", N.63°E., 32 links. PLS William Ives, DS, 1850. Set quarter section post. Sugar 16", S.67°W., 46 links. \*\*\*\* Alger County. W.W. Gleason, CS, 1913. Set iron corner post from original BT. No references. \*\*\*\*\* Michigan Department of Conservation, Forestry Division. Billy D. Buckler, RLS, 1960. Found 2" iron pipe with 3" brass cap set by unknown party. Distances to corners check fairly well. Maple 6", (4S NBT) N.68°W., 15 links. Maple 10" (4S NBT) S.18°W., 18 links. Liber 2, Page 199, Alger County corner records. \*\*\*\*\* No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 2" iron pipe with 3" brass cap and 2 NBT's of the 1960 report in good condition. Monument position as found is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Existing 2" iron pipe with 3" brass cap as found. Renewed NBT's with BT signs and paint. Established reference trees with ET signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: Ex. NBT, Maple 16", S.29°W., 12.50 feet (blaze scars); Ex. NBT, Maple 8", N.63°W., 10.09 feet (blaze scars); Maple 12", N.47°E., 49.30 feet (4S BT); Maple 12", S.59°E., 36.00 feet (4S BT). Survey marker sign on 6 foot steel post, N.82°W., 1.5 feet. All bearings are magnetic. TE OF MICH

ROBERT L. **JAMROS** PROFESSIONAL SURVEYOR No 25849 POFESSIONAL

Surveyor's Michigar/License No.