

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Alger (County)	Located In:	Corner Code #
1. Public Land Survey	T 47N R 17W	11
2. Property Controlling in Section	S 2 T 47N R 17W	13
3. Miscellaneous Property in Sec.		
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 11 08/01/13 do hereby state  
13 08/06/13  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(11) Corner common to Sections 2-3 T47N-R17W and 34-35 T48N-R17W. 1952 - R.J.Brotherton RLS set 1" iron pipe from U.S. Bearing Tree Sugar 14" N36W 21 links. New BTS: 10" Beech N21.5°E 27 links, 15" Sugar N86°E 18 links. 1960 - Billy D. Buckler RLS recovered a 3" pipe at the position perpetuated by R.J.Brotherton and noted the U.S. BTS Sugar 14" N36°W 21 links, green but chopped out; and Sugar 12" N42°E 25 links, rotten stump bottom. Set 1" pipe with 4" brass cap. 1960 wits: 18" Maple N88°E 18 links, 10" Beech N25°E 27 links, 30" Maple N36°W 21 links (original BT).

(13-Sec. 2) Southeast 1/16 corner, Section 2. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(11) Found the 1960 monument and adjacent 3" pipe disturbed. Removed both and remonumented the 1952 and 1960 position at record bearing and distance from the witnesses of record. The 1960 NBTs are both in good condition. The US BT Maple N36°W 21 links is now a burned stump at record bearing and distance.

(13-Sec. 2) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(11) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
20" Beech N29°E 18.55' mrkd "S25" NBT of record  
25" Sugar S88°E 12.4' "S2" do  
22" Sugar S88°W 19.8' "S3 NBT"  
6" Y.Birch S02°W 37.55' "S3 NBT"  
E= 8045522.246 N= 191659.691

(13) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
9" Maple S67°E 20.35' mrkd "SE1/16 BT"  
10" Sugar S75°W 21.2' do  
7" Sugar N54°W 25.45' do  
5" Sugar N10°W 9.3' do  
E= 8046738.895 N= 190452.640

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).  
Coord. Ref.=NGS PID DJ8902: N= 177197.949 m. E= 8027768.701 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 08/29/2013

For the Michigan Department of Natural Resources, Forest Resources Division

