

SURVEY & MONUMENTATION

JAN 18 2001

Approved by Alger County
Land Survey Monumentation
Peer Group Under Act 345 of
P.A. of 1990 On 12-13-2000

Hugh W. Carlson
Chairman

05-228

For corners in

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Alger

(County)

Located In:

Corner Code #

FILED

TIME 8:50 AM

DEC 20 2000

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

- | | | | | | |
|--------------------------------------|---|-----|---|-----|-----|
| 1. Public Land Survey | T | 47N | R | 22W | G09 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | T | | R | |
| | S | T | | R | |
| 3. Miscellaneous Property in Section | S | T | | R | |
| | S | T | | R | |

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Robert L. Jamros, in a field survey on June 10, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G09: PLS Alfred Millard, DS, 1852. Corrected between Sections 27 and 28. Set post corner of Sections 21, 22, 27 and 28. Hemlock 12", S.42°W., 9 links. Hemlock 12", N.42°E., 25 links. ***** C.C.I. Co., Land and Timber reports. S. Lowney, Jr., cruiser, 1943 and 1944. Kyle Edwards, cruiser, 1984. Both cruisers found an iron pipe with brass cap. Unrecorded reports. ***** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G09: Found 2" cast steel monument with 3/4" brass cap stamped to identify, dated November 4, 1910. Also found a Hemlock bearing Northwest with face blaze scar, source unknown. Corner monument believed to be set by L.E. Adams, County Surveyor, 1909-1913. No record was found as part of the research for this corner. No original evidence was found. Corner monument as found is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G09: Existing 2" cast steel monument with 3/4" brass cap. Established reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: Maple 6", S.32°E., 32.75 feet (S27 BT); Maple 8", S.35°W., 8.78 feet (BT); Ex. BT, Hemlock 7", N.48°W., 3.39 feet (BT); Maple 6", N.68°E., 33.07 feet (S22 BT). Survey marker sign on 6 foot steel post, S.22°E., 1.1 feet. All bearings are magnetic.

Signed by

Robert L. Jamros

Date Dec. 17, 2000

Surveyor's Michigan License No.

25849

