

SURVEY & MONUMENTATION

JAN 18 2001

For corners in

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Approved by _____
Land Survey Board, under the
Peer Group Under Act 74 of
P.A. of 1970 On 12-13-2000
Gerold W. Adair
Chairman

05-207

Alger
(County)

Located In:

Corner Code #

- | | | | | | |
|-------------------------|---|-----|---|-----|-----|
| 1. Public Land Survey | T | 48N | R | 15W | C08 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling | S | | T | | |
| in Section | S | | T | | |
| 3. Miscellaneous | S | | T | | |
| Property in Section | S | | T | | |
4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

FILED

TIME 8:50 AM

DEC 20 2000

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

I, Robert L. Jamros, in a field survey on April 18, 2000,
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, recovered, found
as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C08: PLS Geo. E. Adair, DS, 1851. Set quarter section post. Beech 6", N.45°W., 17 links.
Hemlock 16", S.10°E., 11 links. ***** Michigan Department of Conservation, Forestry Division.
Dean C. DeLaMater, RLS, 1953. Set 1" iron pipe with 4" brass cap at proportionate measurement
between section corners. W. Pine 14", S.31°W., 98 links. W. Pine stump 28", N.48°E., 77
links. Liber 2, Page 26, Alger County corner records. ***** No other subsequent restoration
of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C08: Found 1" iron pipe with 4" brass cap and 1 NBT of the 1953 report in good condition.
Reference in the Northeast bearing lost. Existing corner monument lies 2.6 feet North and
2.4 feet West of the midpoint position between section corners. Existing corner monument as
found is accepted as a careful and faithful reestablishment of the position of the original
corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C08: Existing 1" iron pipe with 4" brass cap found as found. Renewed existing NBT with BT
signs and paint. Established additional reference trees with BT signs, blazed, scribed and
painted. Set PK nails for measure with aluminum I.D. washers in the following: Ex. NBT, W.
Pine 40", S.35°W., 65.20 feet (blaze scars); Twin W. Pine 7", N.69°W., 23.60 feet (BT); R.
Pine 14", N.69°E., 81.50 feet (1/4S BT); R. Pine 14", S.42°E., 83.00 feet (1/4S BT). Survey
marker sign on 6 foot steel post, N.32°E., 1.0 feet. All bearings are magnetic.

Signed by

Robert L. Jamros

Date

Dec 17, 2000

Surveyor's Michigan License No.

25849

