

JAN 182001

**************************************				Approved by Alger County
JAN 182001				Lend Survey Flormenumentation Peer Group Under Act 345 of P.A. of 1990 On 12-(3, 7) 2400
	A production of the second	LAND CORNER B	ECORDATION CERTI	
For corners in	PECTION		nt of Act 74, Mich. P.	
Alge	LO	cated in:	Corner Code #	05-212
(003)				FILED
1. Public Land S	urvey	T 48N R 15W	н09	TIME 8:50 AM.
		T R T R		DEC 2 0 2000
		T R		
Property Cont in Section	rolling S S	T R T R		DONALD W. KINNUNEN REGISTER OF DEEDS
3. Miscellaneous	s S	_T R		ALGER COUNTY, MI
Property in Se	ection S	_T R		Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat				
5. Private Claims				
				2
				4 7 8 9 10 11 12
Robert L.	Jamros , in a field si	urvey onSeptember	26 200	0 , 5
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current				
manual of survey instructions of the United States Department of the Interior, Bureau of Land				
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 8 19 20 21 22 23 24 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a				
Decree of a Court of Law; established, re-established, monumented, recovered, found				found
as expressed below.				
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.				
A. Description of original monument and accessories and/or subsequent restoration:				
HO9: PLS Geo. E. Adair, DS, 1851. Set quarter section post. W. Pine 15", N.25°W., 43				
links. Beech 8", S.65°E., 04 links. ***** Michigan Department of Conservation, Forestry Division. Dean C. DeLaMater, RLS 1954. Set 1" iron pipe with 4" brass cap from 1 original BT, in fair condition and definite stake remains at corner. W. Pine stump 24", N.01°E., 79 links. W. Pine stump 24", S.60°W., 30 links. Liber 2, Page 69, Alger County corner records. ***** No other subsequent restoration of record.				
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: H09: Found 1" iron pipe with 4" brass cap and 1 NBT of the 1954 report in good condition. NBT bearing Southwest from corner has been destroyed and lost. Corner monument as found is accepted as a careful and faithful perpetuation of the position of the original corner.				
			'	
C. Description	of monument for cor	ner and accessories es	tablished to perpetuate	locating the position of the corner:
HO9: Existing 1" iron pipe with 4" brass cap as found. Renewed existing NBT with BT signs				
and paint. Established new references with BT signs, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: Ex. NBT, W. Pine stump 24", N.07°E., 53.29 feet (NBT); W. Pine stump 20", N.59°W., 60.31 feet (BT); W. Pine stump 22", S.62°W., 75.81 feet BT); W. Pine stub 18", S.15°E., 93.64 feet (BT). Survey marker sign on 6 foot steel post, S.50°W., 1.4 feet. All bearings are magnetic.				
STATE OF MICHIGAN				
				ROBERT L.
	\bigcirc	$\dot{\wedge}$		jamros }
Signed by	Robert 7	6. Carrier	Dete	PROFESSIONAL SURVEYOR No.
25849				
Surveyor's Michi	gan License No	/ 25849		POFESSIONA