

## JAN 182001

"N Sur 1	"TO MEDIMIEN	HAHON		Approved by Alger County
	JAN 182	001		Land Survey Homonumentation Peer Group Under Act 345 of P.A. of 1990 On 12-13 is 2
For corners in	SECTION	N.	R RECORDATION CERT	IFICATE Genalla Catalian
	jer unty)	Located In:	Corner Code #	05-215
1. Public Land	Survey	T 48N R 15W	<i>J</i> 07	FILED TIME Siso Am.
Property Cor in Section     Miscellaneou Property in S	S S	T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R T R R T R		DEC 20 2000  DONALD W. KINNUNEN REGISTER OF DEEDS ALGER COUNTY, MI  Register of Deeds Stamp & File Number
4. Lot No  5. Private Claim	, Record	ded Plat		A B C D E F G H I J K L N
do hereby state the in lines 1 and 2 abor manual of survey Management or by 5 above were in concrete of a Court as expressed belo NOTE: Not mor	hat under requirem ove were in conform instructions of the y a decree of a Co- conformance with the of Law; established w:	mance with regulations and r the United States Departm	A. of 1970, the corner points mer ules therefore as required in the nent of the Interior, Bureau of owner points mentioned in lines 3 pard of Land Surveyors of ted, recovered	f Land 7
A. Description	of original mon	ument and accessories a	and/or subsequent restoration	13 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

**J07:** Established corner position at the midpoint and on line between section corners ⅓ mile East and West. Post and Sugar BT of 1967 report lost and only remains of the Tamarack BT decayed stump are evident. Post position located for decayed Tamarack stump lies approximately 20 feet East and 6 feet South of midpoint position. G.L.O. call on East side of small lake to corner is 0.95 chains, as measured. This date the return is 0.85 chains. Corner position at midpoint and on line is accepted as a careful and faithful reestablishment of the position of the original corner.

J07: PLS Geo. E. Adair, DS, 1851. Set quarter section post. Spruce 7", N.21°E., 20 links. W. Pine 10", S.58°W., 09 links. \*\*\*\*\* C.C.I. Co. T.J. McLaren, cruiser. Set post from original BT, W. Pine stump, S.58°W., 09 links. Sugar 3", N.40°E., 33½ links. Tamarack 6", S.23°E., 07 links. Unrecorded report of 1967. \*\*\*\*\* No other subsequent restoration of

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**J07:** Set  $2\frac{1}{2}$ " x 30" Berntsen aluminum monument no. A1NB30 with  $3\frac{1}{2}$ " aluminum cap stamped to identify corner position. Established reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: Spruce 7", N.14°E., 14.48 feet (4S BT); Balsam 5", N.63°E., 16.72 feet (4S BT); Hemlock 7", S.33°E., 28.37 feet (4S BT); W. Pine 14", S.00°E., 19.35 feet (4S BT). Survey marker sign on 6 foot steel post, S.80°W., 1.0 feet. All bearings are magnetic. E OF MICH

Surveyor's Michigan License No. 25849

record.

Date Dec.

ROBERT L. JAMROS PROFESSIONAL SURVEYOR No.