MAR 6 7 2000

SECTION

ALLEGAN COUNTY REMONUMENTATION

For corners in	· ·
Allegan Located In: Corner Code #	REGISTER OF CHANGE
1. Public Land Survey	
2. Property Controlling STR	Register of Deeds Charles & French
4. Lot No, Recorded Plat	Register of Deeds Stamp & File Number
5. Private Claims	1 A B C D E F G H I J K L
I, <u>Kirk L Van Orde</u> , rin a field survey on <u>Dec 16</u> , 1999 do herebrequirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and conformance with regulations and rules therefore as required in the current manual of survey United States Department of the Interior, Bureau of Land Management or by a decree of a Cothat the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rule Board of Land Surveyors or by a Decree of a Court of Law; established, re-established recovered, found as expressed below:	by state that under 4 7 8 9 10 11 12 12 12 14 15 16 16 16 16 16 16 16 16 16 16 16 16 16
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	9 10 - 30 - 29 - 28 - 27 - 26 - 25 - 11 12 - 31 - 32 - 33 - 34 - 35 - 36
A. Description of original monument and accessories and/or subsequent restorate	ion:
K-5 (1) GLO post established by U.S. Deputy Surveyor C. Britain North between Sections 13 & 14 80.00 set post cor. Sections 11, 12, 13 & 14 Beech 14 N19W 5 links Maple 11 S31E 21 links	
B. Description of corner evidence found and/or method applied in restoring or res	ntinued on back of sheet)
Fd. standard Allegan Co. Remon. monument accessories: S65W 57.0', SE cor. tel. box (M - 57.04 S20E 83.58', PK nail in power pole (M - S75W 45.3', Face of stop sign post 24" poplar N35°W 146.92' C/L tele. pedestal S,SW 124.80' And is accepted as a careful and faithful the original corner. Peer group approved Dec. 28, 1999. C. Description of monument for corner and accessories established to perpetuate to K-5 Standard Allegan Co. Remon. monument (3/4 #23520) in mon. box	t in mon. box and the following () 84.72' to PK & Brass Tag) l perpetuation of the position of ocating the position of the corner:
Nail & Remon. tag in S side 16" maple Nail & Remon. tag in NE side power pole Nail & Remon. tag in NW side power pole Nail & Brass tag in NE side power pole SE corner tele. pedestal Nail in S side 24" poplar	N75°E 99.28' S20°E 84.74' S20°W 83.52' S20°E 84.72' S65°W 57.04' N75°W 0F M/C
Signed by	Date 12/30. ABDD
Surveyor's Michigan License No. 23520	VAN ORDER PROFESSIONAL
APPROVED REMONUMENTATION CORNER	N SURVEYOR

APPROVED REMONUMENTATION CORNER
P.A. 345 OF 1990
ALLEGAN COUNTY
PAPPROVED
COUNTY REP.

FORM APPROVED BY MICH Page 1 of 2

L SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995

PROFESSIONAL SURVEYOR

POFESSIONAL

MAR 0 7 2000

SECTION

```
Section A (continued from Page 1)
<u>K-5</u>
```

```
Ganges Twp., T.2N., R.16W.
     D.A. Ratekin & Associates, Inc. survey Job #77-3728 dated May 12, 1977 shows 5/8" iron @ SE cor. Sec. 11, T.2N., R.16W.
P. pole 83.58'
                                                  79.2
        Fe. cor. post
                                     N75°E
                                     N30°W
                                                  48.3'
        St. sign
                                      S65°W
                                                  58.16'
        SE cor. tel. outlet
     D.A. Ratekin & Associates, Inc. survey Job #79-5577 dated Aug. 8, 1979
(3)
      shows corner found, but does not show ties
      Tri-County Land Surveys, P.C. survey recorded in L. 1099, P. 778, dated May 25, 1984
(4)
      5/8" iron
                                83.58' to PK nail
      Power pole S30°1
Fence corner post
                      S30°E
                                        79.2'
                              N75°E
                    N30°W
                               48.3' at bottom
      St. sign
                                                       58.16' (East outlet)
      SE corner of telephone outlet
                                            S65°W
      Kirk L. Van Order survey Job #91-2509 dated Oct. 3, 1991
(5)
      Fd. 1" iron in mon. box
                                            61.0'
                                    N,NE
      C/L gas marker post
                                            124.80'
      C/L tele. pedestal
                                    S,SW
                                            83.54
                                    S,SW
      LCRC recorded in L. 004, P. 206, by Gary C. Bilow, DNR Surveyor, dated
      Power pole
 (6)
      March 9, 1993
      Found 3/4" iron bar in mon. box and two of Moored's witnesses.
       Accepted this corner as the best evidence of the original GLO post
       3/4" iron bar in mon. box
               57.0', SE cor. tele. box
       S65W
       S20E 83.58', PK nail in power pole
N45E 48.14', PK nail in sq. fence post
S75W 95.3', Stop sign post
Holland Eng., Inc. info
```

(7) Same as in No. 2 and No. 7

Thomas W. Benson, DNR Surveyor, info dated Aug. 29, 1995 Found 3/4" rerod in monument box and three of Bilow's accessories (8) Replaced 3/4" rerod with standard Allegan Co. Remon. 3/4" x 24" iron with red cap 23520 57.0', SE cor. tel. box 83.58', PK nail in power pole S65W **S20E**

S75W 45.3', Face of stop sign post N30E 51.2', Top centerline gas shut off pipe Mitchell Survey, Inc. info

(9) Ganges Township K-5Recovered 3/4" bar in mon. box 1995 PP S30°W 83.58' N35°W 146.92' 24" poplar South end 18" CMP s.75°W 52.72' 83.66' S25°E PР