

APR 25 1995

COMMISSION

For corners in

ALLEGAN COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

ALLEGAN
(County)

Located In:

Corner Code ~~==~~

- | | | | |
|-------------------------|------|-------|---------------|
| 1. Public Land Survey | T-3N | R-13W | J-3 |
| | T | R | S 1/4 SEC-2 |
| | T | R | Monterey Twp. |
| | T | R | |
| 2. Property Controlling | S | T | R |
| in Section | S | T | R |
| 3. Miscellaneous | S | T | R |
| Property in Sec. | S | T | R |

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, BASTI, ADDRESS, in a field survey on 30 JUN, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO: WEST CORRECT LINE BETWEEN SECTIONS 2 & 11
40.02 SET QR. SEC POST
PINE 11 N 25 E 108 LKS
PINE 8 N 05 W 108 LKS

L.C.R.C. L-1, P-154

L.C.R.C. L-1, P-261

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FD. 5/8" IRON PER L.C.R.C.'S

THIS CORNER IS ACCEPTED AS A CAREFUL AND FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER.

APPROVED REMONUMENTATION CORNER
P.A. 345 OF 1990
ALLEGAN COUNTY

DATE APPROVED 7-12-94
COUNTY REP. Mark L. Van Ooster

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

REPLACED 5/8" IRON W/ STD. ALLEGAN CO. MON. (3/4" X 24" STEEL PIN W/ CAP)

1/2" IRON W/ CAP S 25 W 75.00'

1/2" IRON W/ CAP	S 25 W	150.00'
------------------	--------	---------


NOTE: BOTH IRONS ARE ON SAME LINE TO 1/4 COR

16d & REMON TAG W SDE PP S 20 E 277.00'

16d & REMON TAG S SDE PP N 65 E 267.46'

16d & REMON TAG W SDE 10" POPLAR NORTH 102.84'

SE COR CONC FND (HSE #2711) N 60 W 230.08'



Signed by [Signature]
Surveyor's Michigan License No. 30075

Date 22 Aug 74

Surveyor's Michigan License No. 30075

LINE 0005 PAGE 033

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983