

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Allegan

(County)	Located In:	Corner Code #
1. Public Land Survey	T 3N R 13W T 3N R 13W T R T R	A3 A4
2. Property Controlling in Section	S T R S T R	
3. Miscellaneous Property in Sec.	S T R S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Gary C. Bilow, in a field survey on A4 April 19, 1993
A3 July 11, 1992, 19_____,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

A3: Post established by U.S. Deputy Surveyor L. Lyon in 1831 - accessories: Pine 19 S9E 68 links and Pine 11 N59E 63 links. Records
obtained from K. Van Order (PS #23520) dated 11-26-90 State "Set capped iron - accessories: 11" White Oak NE 50.35', 13" twin Maple NNW
46.01', 14" twin Maple NW 67.46', 31" White Oak NNE 22.44', 1-1/2" pipe (M3 T3N R14W) S 34.98".

A4: Post not established by U.S. Government survey. No records found.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A3: Found 1/2" rerod and all of Van Order's witnesses. Distances to corners A2 and M3 per Van Order's survey work sheet checked.
Accepted rerod as the best evidence of the original GLO post.

A4: Established corner equidistant between corners A3 and M5 (M5 & A5 are same corner) on line between corners M3 and M5 (all corners
recorded this date).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A3: Left 1/2" rerod in place
NE 50.35'. Nail in 11" White Oak
NNW 46.01'. Nail in 13" twin Maple
NW 67.46'. Nail in 14" twin Maple
NNE 22.44'. Nail in 31" White Oak
South 34.98', Capped rebar (PS 26453)

A4: Set 1/2" x 24" rebar with plastic
cap stamped "G.C. Bilow LLS 26453"
N12E 47.41', Nail & Tag in 13" twin Oak
N20E 39.16', Nail & Tag in 8" Oak
N72E 52.16', Nail & Tag in 12" Oak
S2W 17.45', Capped rebar (PS 26453)



Signed by Gary C. Bilow Date 5/16/93
Surveyor's Michigan License No. 26453

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

PAGE 100 06139V