

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Antrim
(County)

Located In

Corner Code #

1. Public Land Survey	T	31N	R	6W	M-9
	T	31N	R	6W	L-9
2. Property Controlling in Section	S	T		R	
	S	T		R	
3. Miscellaneous Property in Section	S	T		R	
	S	T		R	

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on December 11, 2006, do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

M-9 G.L.O. 1839 John Hodgson set post for corner sections 24 and 25. Wit: Sugar 12" S43°W 50 links
Hemlock 36" N10°W 11 links

L-9 G.L.O. 1856 E.D. Atwater set quarter section post.
Wit: Sugar 12" N11½°W 29 links
Sugar 6" S52°E 52 links

1962 Kenneth J. Ostling R.L.S. #10068 used this corner to re-established the east ¼ corner of section 25. Type of monument not given.

John E. Ferguson R.L.S. #24595 certificate of survey shows a found 5/8" rod for corner

Wit: 8" Maple	S70°W	24.05'
12" Maple	S05°E	17.45'
8" Maple	N00°E	17.15'
18" Maple	East	21.00'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

M-9 Land owner to the North (Patrick Brennan) found 1" bar listed below laying on the ground he reset 1" bar from memory, he thought it should be plus or minus 15'. Re-established the NE corner of section 25 by doubling up the East quarter of section 25 from the Southeast corner of section 25 to fit K.J. Ostling survey in the area.

L-9 Found 5/8" iron rod fitting J.E. Ferguson's survey in section 24.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-9 Set 1" X 32" pipe with Standard DNR cap
Wit: 14" Y. Birch S81°E 3.47'
15" Maple N18°E 38.74'
8" Hemlock N40°W 32.10'
14" Y. Birch S78°W 31.94'
1" Bar S22°E 11.70'

L-9 Added P.S. cap #33981 to found 5/8" iron bar
Wit: 10" Maple N23°E 17.55'
18" Cherry S63°E 22.06'
14" Maple S40°W 18.29'
7" Maple N87°W 24.55'
Blue Carsonite Post North 1'±

Signed by:

Carl T. Kiiskila

Date:

2-15-07

Surveyor's Michigan License No.:

33981

