Arenac County Remonumentation 02 PAGE 56 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Arenac Corner Code # 1. Public Land Survey 18N R 4E H 9 R 2. Property Controlling R in Section S R 3. Miscellaneous S T R Property in Section Register of Deeds Stamp & File Number 4 Lot No. 5. Private Claims Craig W. McVean in a field survey on May 22 ,19 95

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found Craig W. McVean as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: H 9 - Set 1/4 Section Post - J. Burt - 1843, Hemlk 11" N 80 1/2" E 27 Lks. W. Pine 26" S 30° W 5 Lks. MDOT Witness Card - L. 1, P. 185 - References to 1/4 corner cor to Section 22 and 27, T18N, R4E - found stake and stone from Country Surveyor's records, placed 1" pipe along side - tils angle to G 9 and 19 - Caldwell - 1964.

CPCo Witness Sheet - 4" pine stake - no date. Arenac County Surveyor Notes - Reference to H 9 with distance to G 9 - 1904. Arenac County Surveyor Notes - Reference to H 9 with distance to I 9 - 1905. Arenac County Surveyor Notes - Reference to H 9 with distance to I 9, H 8, and H 7 - 1908. E. Description of comer evidence found and/or method applied in restoring or reestablishing corner: H.9 - Found 1/2" x 18" rebar at surface - bent in tine with fence to S and occupation N. Excavate and find 0.15' dia. x 1.2' long wood stake - down 1' with 1.1' x 0.7' x 0.5' granite stone on SW side and small cobbles under. No evidence of 1" pipe was found - probably plowed out. Dist. and angle ties E and W agree per MDOT Witness Card. Accept stake as comer and replace with 3" Arenac County brass cap on 5/8" x 24" rebar with 4" plastic tile sleeve with concrete. Place stones on N and S side. Monument accepted as the best available evidence of the position of the original corner. C. Description of monument for comer and accessories established to perpetuate locating the position of the corner H 9 - 3" Arenac County brass cap on 5/8" x 24" rebar with 4" plastic tile sleeve with concrete.

S 06" W 30.24" to set nail and tag on E side U.P.

S 09" E 96.18" to NW corner block foundation house.

N 13" E 28.84" to found nail in E side 10" spruce.

N 35" E 105.32" to SW corner block foundation house #4238.

N 50" E 132.80" to SE corner block foundation house #4238.

N 10" E 50.17" to found nail in E side U.P.

S 10" W (S 03" W - CPCo.) 27.60" (28.00 - CPCo.) to centerline Rotted off wood anchor post. OF MICH CRAIG W MOVEAN PROFESSIONAL SURVEYOR 39088 off wood anchor post.

REVISED JAN

Surveyor's Michigan License No.