

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 47N R 34W T T	D9
2. Property Controlling in Section	S 5 T 47N R 34W S S	11
3. Miscellaneous Property in Sec.	S S S	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on D9 08/13/12 do hereby state  
11 08/09/12  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D9) Quarter corner common to Sections 20 and 29. 1852 - Established by Z.B.Searles Deputy Surveyor  
midway and on the Section line between Section corners 39.85 chains east and west. Sugar 4" at 1/4  
cor. Y.Birch 28" S78W 21 links.

(11) Southwest 1/16 corner, Section 5. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D9) The original post and accessories were not recovered. Found no acceptable evidence of the  
position of the original corner on the ground. Reestablished the position for the corner midway and  
on the Section line between Section corners 2627.90' east and west.

(11) Established the position for the corner at the intersection of straight lines connecting  
opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D9) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
5" Sugar N70°E 17.6' mrkd "1/4S NBT"  
8" Sugar S63°E 22.2' do  
12" Sugar S84°W 15.4' do  
9" Sugar N26°W 11.7' do  
Set sq'd Cedar post adjacent.

(11) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Made firm in a mound of rock 3' dia.x1.5' high  
Set measuring nail with MDNR tag in the side of:  
9" Sugar N03°E 36.4' mrkd "1/16S BT"  
10" Sugar S83°E 15.8' do  
4" Sugar S52°E 5.0' do  
7" Sugar S46°W 2.1' do  
Set sq'd Cedar post adjacent.

Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 01/02/2013

For the Michigan Department of Natural Resources, Forest Resources Division

