

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 48N R 32W	E5 (GCDB 300500)
2. Property Controlling in Section	S 9 T 48N R 32W	14 (GCDB 400520)
3. Miscellaneous Property in Sec.	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 06/09/14 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(14-Sec. 9) South 1/16 corner between Sections 9 and 10. Not previously monumented.

(E5) Corner common to Sections 8-9-16-17. 1975 - Remonumented in 1975 by K.L.Sackett RLS. 1998 -  
The undersigned recovered the 1975 position and monument in good condition and made new witnesses:  
1" ID I.pipe with 4" aluminum cap at the corner; 11" W.Spruce N05°E 30.4'; 11" W.Spruce N55°E 41.5';  
9" Balsam S18°E 25.8'; 4" Balsam S58°W 22.0'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(14-Sec. 9) Established the position for the corner midway and on the Section line between Section  
corner 1297.36' south and Quarter corner 1297.36' north.

(E5) Found the 1975 monument in good condition and at record bearing and distance from the two  
remaining 1998 NBTs: 11" W.Spruce N05°E 30.4', and 4" Balsam S58°W 22.0'. Accepted the monument as  
the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(14) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
10" B.Spruce N43°E 5.0' mrkd "1/16S BT"  
8" B.Spruce S54°E 12.2' do  
4" Balsam S17°W 16.8' do  
7" B.Spruce N50°W 16.0' do  
Set sq'd cedar post adjacent.  
E= 7900041.314 N= 199159.194

(E5) Found 1"ID I.pipe with 4" alum. cap.  
Set measuring nail with MDNR tag in the side of:  
5" Balsam S57°W 22.1' old blazes (1998 NBT)  
12" Spruce N07°E 31.1' do do  
5" Balsam S01°W 13.1' mrkd "S17 NBT"  
7" Maple N33°W 17.4' "S8 NBT"  
Sq'd cedar post adjacent.  
E= 7898426.846 N= 198760.617

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)  
Coord. Ref.=NGS PID RL1468: N= 199449.721 m. E= 7900600.011 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 06/18/2014

For the Michigan Department of Natural Resources, Forest Resources Division

