

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 48N R 32W	C3
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S 17 T 48N R 32W	8
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3			7		8		9		10		11		12
4													
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 10 03/20/2012 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(C3) Section corner common to Sections 5-6-7-8. 1975 - The original post and accessories were not
recovered. Corner remonumented by K.L.Sackett RLS at the location of a found post and old Ford Motor
Co. location poster. Set 1"IDx36" Iron pipe with 4" aluminum cap. 24" Sugar N39W 10.6', 8" Sugar
S08E 28.2', 22" Sugar N52E 12.7'. Found no other record.

(8-Sec. 17) West 1/16 corner, Section 17. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C3) Found the 1975 monument in good condition and at record bearing and distance from the two
remaining NBTs. The Sugar NBTs NE and SE are in good condition with overgrown blazes. Accepted the
monument as the best available evidence of the position of the original corner.

(8-Sec. 17) Established the position for the corner midway and on a straight line between Quarter
corner 1322.34' west and Center of Section 17 1322.34' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C3) Found 1"ID I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
22" Sugar N59E 13.65' old blazes (1975 NBT)
12" Sugar S02E 28.6' do do
4" Sugar N48W 12.95' mrkd "S6 NBT"
10" Maple S35E 26.0' mrkd "S8 NBT"
Bearings are magnetic.

(8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
9" Sugar N36E 16.15' mrkd "1/16S BT"
12" Y.Birch S43E 12.65' do
9" Y.Birch S37W 13.75' do
7" Sugar N46W 3.35' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 04/04/2012

For the Michigan Department of Natural Resources, Forest Resources Division

