

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Baraga

(County)

Located In:

Corner Code #

1. Public Land Survey

T 49N R 32W H11  
T 49N R 32W I12  
T R  
T R  
T R  
T R  
T R  
T R  
T R  
T R

2. Property Controlling  
in Section

S T R  
S T R  
S T R  
S T R  
S T R  
S T R  
S T R  
S T R  
S T R  
S T R

3. Miscellaneous  
Property in Sec.

4. Lot No. , Recorded Plat  
5. Private Claims

Apr 25 2005

I, Stephan J. Szyszkoski, in a field survey on                     , 19        do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

(H11) Quarter corner common to Sections 27-34. 1852: Established by Guy Carleton, Deputy Surveyor "N89 56W corrected between Secs. 27&34 ... 39.80 Set quarter post. Sugar 10 N34W 53 links, Yellow Birch 8 S27E 20 links ... 79.60 Section corner". Found no subsequent record.

(I12) Quarter corner common to Sections 34-35. 1852: Established by Guy Carleton, Deputy Surveyor: "N6'W corrected between Sections 34&35 ... 40.10 Set quarter post. Fir 8 S70W 31 links, Yellow Birch 20 N40E 15 links ... 80.20 Set post corner of Secs. 26-27-34-35". Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(H11) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the corner midway between and on the section line defined by monumented Section corners 2610.33' east and west. The corner position falls on a south-facing rocky slope. Monument was made firm in a mound of rock 2'x3'x1' high.

(I12) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the corner midway and on a line between Section corners 2687.57' north and south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(H11) Set 1"IDx32" I.pipe with 4" alum.  
MDNR cap. Set measuring nails in:  
19" W.Pine N62E 37.9' mrkd "1/4S NBT"  
6" Maple S34E 9.4' do  
7" Sugar S76W 17.2' do  
6" Sugar N23W 18.2' do  
Set sq'd cedar post adjacent. Bearings  
are magnetic. Distances are to nail  
with tag.

(I12) Set 1"IDx32" I.pipe with 4" alum.  
MDNR cap. Set measuring nails in:  
20" W.Pine N43W 30.9' mrkd "1/4S NBT"  
14" W.Pine N49E 65.2' do  
4" Sugar S13E 3.65' do  
11" Sugar S59W 37.4' do  
Set sq'd cedar post adjacent. Bearings  
are magnetic. Distances are to nail  
with tag.



Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 6/13/05