

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 49N R 32W	E11
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 07/08/2009 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E11) Corner common to Sections 28-29-32-33. 1852 - Established by Guy Carleton Deputy Surveyor.
Set post. Sugar 12" S16E 27 links, Sugar 14" N40W 28 links. 1988 - Remonumented by K.L.Sackett RLS:
"Original monument and accessories not found. Found 4" squared post, signature tree and location
poster. Restored [corner] at old post. Fits good with land calls and has been used for many years".
Mr. Sackett set a 1"IDx36" I.pipe with 4" aluminum cap at the corner position. Witnesses: 4" Sugar
N17E 9.8', 6" Sugar N25W 15.7', 4" Sugar S36W 16.0'. Distances to notch in lower blaze.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E11) Found the 1988 monument in good condition and at record bearing and distance from two of the
three 1988 NBTs. The Sugars NW and NE were found in good condition with overgrown blazes. Accepted
the monument as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E11) Fd. 1"ID I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
8" Sugar N22W 16.2' old blazes (1988 NBT)
7" Sugar N21E 9.8' do do
8" Sugar S20E 21.6' mrkd "S33 NBT"
8" Sugar S87W 13.5' "S32 NBT"
Sq'd Cedar post adjacent.
Bearings are magnetic.



Signed by Stephan J. Szyszkoski Date 07/09/2009
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Office of Land and Facilities