

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga Located In: Corner Code #
1. Public Land Survey T 49N R 33W K12
2. Property Controlling in Section S 36 T 49N R 33W 5
3. Miscellaneous Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M) containing numbers 1-36 and survey points.

I, Stephan J. Szyszkoski, in a field survey on 5 08/11/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(K12) Quarter corner common to Sections 35 and 36. 1852 - Established by Z.B.Searles, Deputy, midway and on the Section line between Section corners 40.00 chains north and south. Set Maple post. Y.Birch 12" S65°W 14 links, Fir ... S20°E 40 links. 1941 - Notes of N.T.Thompson RLS state that he found "old Bir. tree looks good" at a distance that appears to have been 2637' from Section corner K11. Set post and new BTs: Maple 8" N72°W 15 ft.; Y.Bir. 10" N43°E 7 ft. 8 in.

(5-Sec. 36) Center-North 1/16 corner, Section 36. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(K12) Found a 1-1/4" ID Iron pipe projecting 12" a.g., top mushroomed, with cedar post adjacent, at record bearing and distance from the 1941 NBTs Y.Birch 10" N43°E 7.7', now a 4' high rotted stub, and Maple 8" N72°W 15 ft., now a stump hole. Found the distances to corners north and south to be 2634.96' and 2642.30', respectively, and the pipe to be 3.5' east of a straight line between them. The original BT Y.Birch was not recovered. Accepted the monument as a careful and faithful perpetuation of the position of the original corner.

(5-Sec. 36) Established the position for the corner midway and on a straight line between Quarter corner 1312.05' north and the Center of Section 36 1312.05' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K12) Found 1.25" ID I.pipe with mushroomed top. Set measuring nail with MDNR tag in the side of: 10" Spruce N08°W 10.1' mrkd "1/4S NBT" 5" Sugar N83°E 16.2' do 12" Y.Birch S24°E 16.15' do 8" Sugar N66°W 9.85' do E= 7893765.322 N= 202846.497

(5) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 7" Sugar N32°E 31.6' mrkd "1/16S BT" 4" Spruce N83°E 11.5' do 7" Sugar S33°W 23.45' do 6" Maple N80°W 38.05' do Set sq'd cedar post adjacent. E= 7894571.030 N= 203231.535

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum. Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Signed by [Signature] Surveyor's Michigan License No. 33986

Date 10/27/2015

For the Michigan Department of Natural Resources, Forest Resources Division

