

LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: See below

For corner(s) in: Baraga County

Original Public Land Survey Corner

Corner Code

a. S T 49N R 33W J09 (GCDB 540300)
b. S T 49N R 33W K09 (GCDB 600300)
S T R
S T R

Property Corner

1/16 Corner Code

S T R
S T R
S T R
S T R



1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13	A	B	C	D	E	F	G	H	I	J	K	L	M	13

Part A. Corner History

a.) Quarter corner common to Sections 23 and 26. 1852 - Established by Zelotes B. Searles, Deputy, midway and on the Section line between Section corners 40.035 chains East and West. Set post. Heml. 24" S48°W 25 links, Y.Birch 14" N75°E 21 links. 1944 - Norman T. Thompson, RLS found both BTs down and set iron pipe with hemlock post. New BT Sugar 14" S40°E 22.4'.

b.) Section corner common to Sections 23-24-25-26. 1852 - Established by Zelotes B. Searles, Deputy. Set post. Y.Birch 12" S57°W 28 links, Fir 12" N49°E 25 links. 1944 - Notes of N.T.Thompson, RLS, state that original BTs are gone. Mr. Thompson reestablished the corner position but did not document the method by which he did it. Set cedar post. New BTs: Sugar 6" N65°W 20.0', Sugar 3" S54°E 14.3'.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a.) Sept. 18, 2017. Found a 1.25" dia. iron pipe at record bearing and distance from the rotting remains of the 1944 NBT Sugar S40°E, 22.4', now a stump. Found rotted cedar post on the ground adjacent to the pipe. No evidence of the original BTs. Courses east and west to adjacent section corners are very consistent, J9 being only 1.2 ft. from the record position midway between section corners. Accepted the pipe as a careful and faithful perpetuation of the position of the original corner and installed a new monument at its position.

b.) Sept. 19, 2017. Found a decaying squared post set in a small rock mound at record bearing and distance from the 1944 witnesses, both recovered in good condition. The Maple N65°W 20.0 ft. shows old overgrown blazes. No overgrowth was observed on the Sugar S54E 14.3', which is now 9" DBH. Courses N-S-E-W all check well with the original record. Accepted the position of the post as a careful and faithful reestablishment of the position of the original corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

a.) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
9" Sugar N38°E 15.4' mrkd "1/4S NBT"
6" Sugar S89°E 12.5' do
7" Sugar S29°E 12.2' do
7" Sugar S51°W 5.25' do
Set sq'd cedar post adjacent.
E= 7893002.476 N= 205262.486

b.) Set 1"IDx28" I.pipe with 2" alum. MDNR cap made firm in a 2' dia.x1.5' tall mound of rock. Set measuring nail with MDNR tag in the side of:
9" Sugar S49°E 14.2' mrkd "S25 NBT" (1944 NBT)
14" Maple N61°W 20.3' "S23 NBT" do
12" Sugar N25°E 9.25' "S24 NBT"
6" Sugar S63°W 9.9' "S26 NBT" fd. Celotex poster on this tree. Set sq'd cedar post adj.
E= 7893800.985 N= 205246.092

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.

Coord. Ref.=NGS PID RL0041: N= 210246.994 m. E= 7895426.985 m.

Stephan J. Szyszkoski

10/16/2017

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908