

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 50N R 33W	A5
	T 50N R 33W	C8
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on A5 05/26/2011 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(A5) Corner common to Sections 7-18 T50N-R33W and Sections 12-13 T50N-R34W. 1846 - Established by  
Austin Burt Deputy Surveyor. Set Fir post. Hemlock 12" S27W 58 links, Hemlock 8" N60E 39 links.

(C8) Quarter corner common to Sections 19 and 20. 1849 - Established by Wm.Burt Deputy Surveyor  
midway and on the Section line between Section corners 40.00 chains north and south. Set Cedar post.  
Spruce 8" N24E 22 links, W.Pine 7" S80W 4 links. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A5) Found a 1"ID Iron pipe with plastic cap stamped "R.D.S. LS 21054" (Richard Supina), in good  
condition. There appear to be overgrown measuring nails in nearby trees to serve as witnesses. No  
blazes or other marks visible. I accepted the pipe as the best available evidence of the position of  
the original corner. From the corner monument, an old Ford Motor Co. location poster was found on a  
16" Maple S79E 6'. The poster appears to have been moved to this tree in recent years.

(C8) The original post and accessories were not recovered. Found no evidence of the position of the  
original corner on the ground. Reestablished the position for the corner midway and on the Section  
line between Section corners 2630.20' north and south, proportionate to the original record  
measurements.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A5) Found 1"ID I.pipe with plas. cap #21054  
Set measuring nail with MDNR tag in the side of:  
16" Maple S79E 5.85 mrkd "S8 NBT"  
4" Sugar S10W 17.3' "S13 NBT"  
4" Sugar S86W 7.0' do  
5" Sugar N19W 6.5' "S12 NBT"  
Set sq'd cedar post adjacent.  
Bearings are magnetic.

(C8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
8" W.Spruce S75E 36.3' mrkd "1/4S NBT"  
7" Maple S66E 28.25' do  
10" Maple S24W 21.5' do  
10" Hemlock S50W 27.6' do  
Set sq'd cedar post adjacent.  
Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 10/24/2011

For the Michigan Department of Natural Resources, Forest Management Division

