LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Baraga		•			
_	(County)	Localed In:	Corner Code ##		
1.	Public Land Survey	T R T R T R			
2.	Property Controlling	S T R S 20 T 50 MR 34 W	14		
,	in Section	S 20T 50MR 34W	14		

Register of Deeds Stamp & File Number

, Recorded Plat _ 4 Lot No.

Property in Sec.

5. Private Claims .

<u>August 09, 1995</u> Stephan J. Szyszkoski in a field survey on _ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

		_		_				_			
L			<u>[</u>	L.	_	_	[_	-	<u>, </u>	L,	
	Ī	L	Ĺ		Ĺ		Ĺ				L
	_			\Box		1	<u>. </u>	1			Ĺ
	Ĺ		Ĭ		Ĺ		Ľ		Ĺ		Ē
L,	Ĺ	L,	ļ	_,	 6—		<u> </u>			L	
Ĺ	Ľ		Ľ.		Ľ		Ľ		Ĺ		Ľ
_,		_,		_,		,	2	_,	<u>, </u>	L,	
Ш	Ľ	_			Ĺ	Ĺ	Ш		Ĺ		Ш
3		_,		_2		_,	,	_,	6—	_,	
لـــا	Ĺ				ĹЦ						Ш
,	Ш		2	3		3	4	3	5		6
تــا	Ĺ	لّـــا	Ū			لَّـــا		_ Ĭ		لّــــا	

- A. Description of original monument and accessories and/or subsequent restoration:
 - (14 A) Witness corner to South 1/16 corner between Section 20-21 on South side of Kelly Lake. Corner not established in the original survey. Found no subsequent record.
 - [14 B] Witness corner to South 1/16 corner between Sections 20-21 on West side of Kelly take. Corner not established in the original survey. Found no subsequent record.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - (14 A) Found no evidence of prior monumentation at the corner position. Established the corner equidistant between quarter corner 1296.53' north and Section corner 1295.53' south and on a straight line between the Section corner and the original line tree recovered 1886.01' north of the section corner. The corner falls in Kelly Lake. I placed a 1"ID x32" iron pipe capped with a 4" dia. cast aluminum MONR tablet, projecting 9°, 296.00' south of the corner, on the section line. The tablet is stamped "T50M R34W S1/16 WC 20/21 COR IS 296' MORTH 8-9-95 PS 33986'. The WC falls on a north facing slope and is 42 ft. south of the swampy margin of Kelly Lake. (14 B) Established the 1/16 corner as described earlier on this LCRC. I placed a second witness corner herein described. Established the MC on the south E-W 1/16 line 384.00 feet west of the 1/16 corner. At the position for the MC, 1 placed a 1°10x32° iron pipe, projecting 8°, and capped with a 4° dia. cast aluminum tablet, stamped " TSON R34W S1/16 20/21 WC. COR IS 384' EAST 8-9-95 PS 33986°. The MC falls on a south facing slope 95' West of the swampy margin of Kelly take.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

 [14 A] Set 1° pipe with MONR cap. (14 8) Set 1° pipe with MONR cap.

[14 A] Set 1" pipe with MDNR cap. Blazed and scribed the following bearing trees: 10" Maple N62E 7.1' WC BT" 6" W. Pine SOIW 13.8' "WC BT" 8' Maple \$37E 7.2' 'WC 8T' 6" Hemlock NSOW 8.6' "WC BT" Bearings are magnetic. Distances are

Blazed and scribed the following bearing trees: "WC RI" 4" Hemlock N46E 20.0' 7" W. Pine S61E 9.3" "WC BT" 12° R. Pine \$60W 23.8' "WC BT" 16" A. Pine N45W 82.0' (slope dist) Distances are horizontal unless noted. Bearings are magnetic. Placed a 3°

squared spruce post adjacent.



Surveyor's Michigan License No. .

horizontal.

For the Michigan Department of Natural Resources - Forest Management Division Revised May 14, 1875