

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>50</u> N. <u>34</u> E. <u>W.</u>	<u>13</u>
2. PROPERTY CONTROLLING IN SECTION_____	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	_____
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on May 6, 19 76, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Sec. Corner 2, 3, 10, & 11, T50N, R34W:
Maple post (Not found. Sec. "B" for subsequent monument)
Y. Pine 36 N19W 8 (" " No subsequent accessories found.)
Sugar 12 S65E 33 (" " No subsequent accessories found.)

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner re-established on line between original sec. corner S0°16.5'E 238.943 ch. and re-established closing corner on 5th Correction Line N0°16.5'W 74.376 ch., at the average latitude of the section corners 1, 2, and 3 miles West of it. As the distances between each of those 3 corners and their corresponding closing corners on the Correction Line are all longer than the record, it seemed reasonable to assume that this one is also long. Experience in retracing some 26 miles of section lines in this township indicates that the original subdividing surveyor was more accurate at maintaining his N & S directions than he was at measuring between corners, thus my opinion that the corner as I have re-established it most accurately reflects its original location. Found a squared cedar post S50°E 83.0 ft. set by unknown persons, but it appears to have been set by measuring eastward the record distance from the corner a mile west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.

Red Maple 8 N45°E (mag.) 11.6 ft. "S2, NBT"
Red Oak 15 N32°W (mag.) 22.4 ft. "S3, NBT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Arthur O. Enger DATE October 20, 1976

MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

