

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 4 T 51N R 32W	8
	S 4 T 51N R 32W	11
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3		KEW.											
4	7	BAY	8	9	10	11	12						
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Stephan J. Szyszkoski, in a field survey on 11 11/08/2011 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(8-Sec. 4) West 1/16 corner, Section 4, being the NE corner of Government Lot 2. Not established in
the original survey. Corner shown as monumented by a 3/4" capped pipe set by S.C.Hein PS on a 1992
survey recorded in Liber 1 of surveys, Page 214.

(11-Sec. 4) Southwest 1/16 corner of Section 4, being the SE corner of Government Lot 2 and the NE
corner of Government Lot 3. The corner is shown as monumented with a 3/4" capped pipe set by
S.C.Hein PS on a 1992 survey recorded in Liber 1 of Surveys, Page 214.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(8-Sec. 4) Established the position for the corner at the intersection of the E-W 1/4 line of Section
4 as monumented by S.C.Hein in 1992 with the West 1/16 line of Section 4. The bearing of the 1/16
line is the mean of the N-S 1/4 line and the West line of Section 4, passing through 1/16 corner #1,
monumented by the B.L.M. in 1986. The 1992 monument was found 35.00' east of this intersection and
was not accepted.

(11-Sec. 4) Established the position for the corner at the intersection of 1/16 lines. The 1992
monument, its easting being in error, was found 17.47' east and was not accepted.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" Maple N22E 6.5' mrkd "1/16S BT"
10" Y.Birch N82E 17.7' do
9" twin Maple S37W 23.4' do
6" Y.Birch N68W 10.1' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

(11) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
12" Cedar N52E 6.8' mrkd "1/16S BT"
9" Ash South 11.6' do
5" Maple N87W 31.6' do
8" Spruce N04W 17.6' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 01/25/2012

For the Michigan Department of Natural Resources, Forest Management Division

