

APR 08 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Baraga
(County)

Located In:

Corner Code #

RECEIVED FOR RECORD THIS 28TH DAY
OF DECEMBER A.D. 1995 AT 10:30 AM
AND RECORDED IN LIBER 4 OF LAND
CORNER RECORDATION ON PAGES
613 - 614.

Nelda J. Robillard
BARAGA COUNTY REGISTER OF DEEDS
Register of Deeds Stamp & File Number

1. Public Land Survey T 51N R 32W F-13
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Section S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Michael Mileski, in a field survey on December, 19 95,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

F13; South One-quarter Corner Section 33, T51N, R32W, on 5th Correction Line.

See back of form.

APPROVED LAND CORNER
P.A. 345 OF 1990
Baraga County
12-19-95
[Signature]

	A	B	C	D	E	F	G	H	I	J	K	L
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F13; South One-quarter Corner Section 33, T51N, R32W, on 5th Correction Line.

Found Mr. Douglas' monument as described in Part A to be in reasonable agreement
with its intended position and with his new bearing trees of record. Accepted as a
careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F13; South One-quarter Corner Section 33, T51N, R32W, on 5th Correction Line.

See back of form.



Signed by *Michael Mileski*

Date 28 December 1995

Surveyor's Michigan License No. 39091

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

A. Description of original monument and accessories and/or subsequent restoration:

F-13; South One-quarter Corner Section 33, T51N, R32W, on 5th Correction Line.

Originally established during U.S. Survey conducted by Austin Burt, D.S. in 1845 and monumented with a wood post. No accessories are noted in the U.S. field notes.

This corner was reestablished at proportionate distance between the southwest corner of Section 33, T51N, R32W and the southeast corner of Section 34, T51N, R32W by Stephen Douglas of the Bureau of Land Management during the course of a survey conducted from 27 May 1985 to 30 September 1986 and approved 17 February 1989. Mr. Douglas monumented the corner with a 2½" dia. aluminum pipe with 3" cap appropriately stamped as to location and noted the following new bearing trees:

Sugar Maple 7 N22°E 53½ lks.

and a

Sugar Maple 9 N14°W 51 lks.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-13; South One-quarter Corner Section 33, T51N, R32W, on 5th Correction Line.

Left existing monument in place adding "PA 345 1995" to the cap.

Set 60d spike	N/side	16" Sugar Maple	S87°E	30.93'
Set 60d spike	SW/side	11" Hemlock	S46°E	30.03'
Set 60d spike	NE/side	4" Sugar Maple	S55°W	26.58'
Set 60d spike	SW/side	8" Red Maple	N45°W	18.42'

All of the above new bearing trees are marked with upper and lower face blazes and scribed "NBT".