

# SURVEY & REMONUMENTATION

MAY 05 1997

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

COMMISSION

Baraga

(County)

Located In:

Corner Code #

1. Public Land Survey

T 51N R 33W

G-9

2. Property Controlling  
in Section

S

T

R

3. Miscellaneous

S

T

R

Property in Sec.

S

T

R

4. Lot No. , Recorded Plat

5. Private Claims

I, Michael Mileski, in a field survey on December, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-9; Section Corner common to Sections 21, 22, 27, and 28, T51N, R33W;

See back of form.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-9; Section Corner common to Sections 21, 22, 27, and 28, T51N, R33W;

Found a railroad spike set over a 3/8" x 11" iron rod. Corner is located at the intersection of the physical centerlines of old US-41 and Tangen Road. Replaced the found iron rod with a 1" (I.D.) x 36" galvanized iron pipe. Accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-9; Section Corner common to Sections 21, 22, 27, and 28, T51N, R33W;

Set a 1" (I.D.) x 36" galvanized iron pipe with a 2" aluminum cap stamped as to location in a monument box.

i)	Set 7" spike	E/side	11" White Pine	N36°E	58.87'
ii)	Set 7" spike	SW/side	10" White Spruce	S36°E	97.57'
iii)	Set 7" spike	NW/side	13" White Pine	S24°W	94.14'
iv)	Set 7" spike	SW/side	5" White Spruce	N45°W	81.74'

(i), (iii), and (iv) are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes as well as a band around the tree at the upper blaze are painted red.

(ii) is not marked.

RECEIVED FOR RECORD THIS 3RD DAY OF JANUARY, 1997 AT 10:30 A.M. AND RECORDED IN LIBER 4 OF LAND CORNER RECORDATION RECORDS ON PAGES 748-749.

*Helda Mc Intyre*  
BARAGA COUNTY REGISTER OF DEEDS

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

APPROVED LAND CORNER  
P.A. 345 OF 1990  
Baraga County

12-18-96



Signed by

Date

Surveyor's Michigan License No. 39091

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

LIBER 4 PAGE 748

REVISED MAY 14, 1975

REVISED JAN., 1983

REVISED OCT., 1995

A. Description of original monument and accessories and/or subsequent restoration:

G-9; Section Corner common to Sections 21, 22, 27, and 28, T51N, R33W;

Originally established during U.S. Survey conducted by Harvey Mellen, D.S. in 1845 and monumented with a wood post witnessed by a

Cedar	14	S34°W	9 lks.
-------	----	-------	--------

Hemlock	24	N31°E	13 lks.
---------	----	-------	---------

This corner was indicated as being monumented with a 3/8" x 12" iron rod by Billy Buckler, RLS #8887 in 1964. Mr. Buckler noted the following accessories:

Power Pole	S41°W	38.0'
Telephone Pole	N48°W	46.5'
Telephone Pole	N30°E	38.5'
Soft Maple	N87°E	28.6'

On 20 October 1983, Robert Crampton, PS #24591 recovered a "3/8 (in.) steel pin found in the centerline of two section line roads and on a projection of an old fence East of the corner". According to a Land Corner Recordation Certificate prepared by Mr. Crampton dated 7 December 1983 and recorded on 9 December 1984 in Liber 4 on page 62 of the Baraga County Land Corner Records, this monument was left in place and the following accessories were established:

12" Maple	S32°E	42.93'
Gone.		

Utility Pole	S40°W	38.48'
Found a small nail and plastic tag on the face.		
Measured	S43°W	38.65'

16" Spruce	N35°W	62.42'
Found an alive Balsam 18" in diameter.		
Measured	N38°W	62.35' to face.

8" Balsam	N72°E	31.31'
Gone.		

During the course of a survey conducted by Stephen Douglas of the Bureau of Land Management from 10 May 1984 to 10 November 1984 and approved 23 September 1985, the 3/8" diameter steel pin as recorded by Mr. Crampton was found and accepted. The BLM did not remonument the corner. Their ties to Mr. Crampton's 1979 accessories are as follows:

Balsam	8	N66°E	47½ lks. (31.35')
Maple	12	S38°E	65 lks. (42.90')
Power Pole		S45°W	58½ lks. (38.61')
Spruce	16	N36°W	94½ lks. (62.37')

SURVEY &  
REMONUMENTATION

MAY 05 1997

COMMISSION