

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 52N R 30W	M6
	T	
	T	
2. Property Controlling in Section	S T	
	S T	
	S T	
3. Miscellaneous Property in Sec.	S T	
	S T	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 11/03/2010 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(M6) Quarter corner common to Section 13 T52N-R30W, Baraga County and Section 18 T52N-R29W, Marquette  
County. 1985 - K.L.Sackett RLS remonumented the corner from an old 40" yellow birch found with axe  
marks and believed to be an original bearing tree. Set 1"IDx32" I.pipe with 4" alum. cap. 16"  
Hemlock N75E 3.0', 12" Hemlock S10E 17.2', 10" Sugar S50W 17.8'. 1990 - G.C.Van Neste RLS used this  
monument to control the subdivision of Section 18 T52N-R29W.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(M6) Found the 1985 monument in good condition and at record bearing and distance from the 1985  
witnesses, all dead with scribing and measuring notch visible. The Y.Birch noted in the 1985 record  
was not found. Accepted the monument as the best available evidence of the position of the original  
corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(M6) Found 1"ID I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
14" Maple N46E 19.25' mrkd "1/4S NBT"  
7" Sugar S28W 11.75' do  
7" Sugar S60W 21.7' do  
16" Cedar N10W 43.3' do  
Set sq'd cedar post adjacent.  
Bearings are magnetic.



Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 02/02/2011

For the Michigan Department of Natural Resources and Environment, Forest Management Division