

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga

(County)

Located In:

Corner Code #

1. Public Land Survey

T 52N R 30W

B13

T 52N R 30W

B12

T R

S

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

Register of Deeds Stamp & File
Number

4. Lot No. , Recorded Plat

5. Private Claims

B12 Jun 16 2005

B13 Jun 30 2005

I, Stephan J. Szyszkoski

, in a field survey on , 20 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of
survey instructions of the United States Department of the Interior, Bureau of Land Management or by a
decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in
conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law;
established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(B13) Quarter corner common to Section 31 T52N-R30W and Section 6 T51N-R30W. 1845 - Established by Wm.A.Burt, Deputy Surveyor: West
on south side of Section 31 ...40.00 Set qr Section post. Spruce 12 N27E 19 links, Cedar 14 N58W 8 links.. ... 80.88 Intersected
Range line 115 links south of temporary post and set post corner of T's 51&52N between R's 30&31W.

(B12) Center of Section 31. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(B13) The original post and accessories were not recovered. Found no monumentation at the corner position. Reestablished the corner
on the section line between monumented C13 2621.92' east and monumented A13 2679.60' west, being proportionate to the original record.
The position for the corner falls approximately in line with Greenhouse road west, produced east, and with Greenhouse road south,
produced north.

(B12) Established the corner at the intersection of straight lines connecting opposite 1/4 corners. From the position thus
established, I found a metal fence post by persons unknown, N62E 17.4' distant.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(B13) Set 1"IDx32" I.pipe with 4" alum.

MDNR cap. Set measuring nails in:

6" Spruce S68E 22.2' mrkd "1/4S NBT"

9" Maple S21E 15.5' do

18" Hemlock S40W 68.3' do

13" Maple N47W 62.6' do

Set sq'd cedar post adjacent. Bearings
are magnetic. Distances are to nail
with tag.

(B12) Set 1"IDx32" I.pipe with 4" alum.

MDNR cap. Set measuring nails in:

7" Y.Birch S47E 8.6' mrkd "C1/4 BT"

7" Hemlock S15E 15.6' do

14" Hemlock S79W 8.7' do

8" Hemlock N42W 2.7' do

Set sq'd cedar post adjacent. Bearings
are magnetic. Distances are to nail
with tag.



Signed by

Stephan J. Szyszkoski

Date

11/22/05

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 19

Revised May 14, 19

Revised Jan., 19

Revised Oct., 19