Land Corner Recordation Certificate

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Craig W. McVean				Field Survey Date: Aug. 2017							
For corner(s) in:	Benzie			County	-	·					
Original Public Land Survey Corner				Corner Code	•						
S	Τ	R									
S	Т	R			A B	C D I	E F (G H	l. J	KLI	\ <i>I</i> I
S	Т	R			1						VI 1
S	Т	R			2 6	- 5	4	3	2	1	2
Property Controlling Corner				Corner Code	3 4 7	- 8	g	10	11	12	3
S	Т	R			- 5	13			13	2	3
S	Т	R				1					5
S	Т	R		48	6 1 8	17	16	15	14	13	6
S	Т	R	#101		7	-				-	7
Property Corner				Corner Code	8 1 9	20	21	22	23	2	8
S 24	Т	26N R	14W	12	_10 30	29	28	27	26	25	10
S	T	R			-11					20	
S	Т	R				000	0.0				11
S	Т	R			- 12 - 31	32 -	33	34	35	36	12
Protracted Public Land Survey Corner				Corner Code	13 A B	CDE	F	3 H	IJ	K L N	13 1
\$ 24	T	26N R	14W	L8							
s	Т	R			_						
S	Т	R			_						
S	Т	R			_						

Part A: Corner History

- <u>L-8</u> C ¼ Corner Sec. 24, T26N, R14W - **1997** Record Survey L. 2, p. 789 & 793
 - R. Max Harris PS #25845 1 ½" iron pipe found.
 - 1) 10" Cherry N82°W 30.04' 2) 6" W. Pine N35°W 19.02' 3) Clp. Maple S36°E 11.21'

 - 4) 10" Maple N54°E 25.24'

- 12 CS 1/16 Corner Sec. 24 -- 1997 Record Survey L. 2, p. 789 & 793 -
 - R. Max Harris PS # 25845 1 $\frac{1}{2}$ " iron pipe found.

 - 1) 8" Maple N4°W 5.33'
 2) 14" Maple S53°W 8.89'
 3) 6" Tw. Ironwood S43°E 21.57'
 - 4) 7" Maple N64°E 17.65'

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

- L8 C ¼ corner Sec. 24, T26N, R14W Found 1 ½" iron pipe in centerline of N-S sand road. Witnesses #2 & 3 are gone. This pipe may be the result of a C.P. Tuller survey indexed in Mitchell and Assoc. records, but the notes apparently are lost. Accepted pipe as the best available evidence of the position of the corner.
- 12 CS 1/16 corner Sec. 24, T26N, R14W Found 1 ¼" I.D. x 1.9' long iron pipe. Wolven wire fence remains N & W. This pipe is S78°49'W 3.04' from the calculated midpoint between 'L8' and 'L9'. This pipe may be the result of a C. P. Tuller survey indexed in Mitchell and Assoc. records, but the notes apparently are lost. Accepted pipe as the best available evidence of the position of the corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

<u>L-8</u> – C ¼ corner Sec. 24, T26N, R14W – 1 ½" iron pipe

N82°W 29.99' to Fd. Nail in S. side 12" Cherry (#1)

N61°E 25.26' to Fd. Nail in SE side 12" S. Maple – Top broken off (#4)

S39°E 47.56' to set N & T in SW side 10" R. Maple

S61°W 33.93' to set N & T in SE side 11" R. Maple

N52°E 38.54' to set N & T in NW side 10" S. Maple

12 - CS 1/16 corner Sec. 24, T26N, R14W Drove stamped 2" Aluminum Cap on 5/8" x 34" long iron rebar into center of found 1 1/4" I.D. iron pipe.
Set Blue Composite Post with loc. tag 1' SE.
N9°W 5.32' to Fd. Nail in E. side 10" S. Maple (#1)
N60°E 17.57' to fd. Nail in NW side 10" S. Maple (#4)

S46°W 8.90' to fd. Nail in N. side 18" S. Maple (#2) S34°E 30.99' to set N & T in W. side 13" S. Maple

CRAIG W.
MCVEAN
PROFESSIONAL
SURVEYOR
No.
39088

Craig W. McVean

Professional Surveyor's License No.: 39088

Prepared By: Craig W. McVean Michigan Dept. of Natural Resources 8015 Mackinaw Trail Cadillac, Michigan 49601