

APPROVED BY THE BERRIEN COUNTY  
SURVEY PEER GROUP AS THE  
OFFICIAL CORNER UNDER MICHIGAN  
PUBLIC ACT 345 OF 1990

RECORDED

Berrien County Remonumentation  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

00 NOV -1 AM 10:39  
BERNICE TRETINEWAY  
REGISTER OF DEEDS  
BERRIEN COUNTY, MICHIGAN

For corners in

Berrien

(County)

Located In:

Corner Code #

- |                         |            |     |
|-------------------------|------------|-----|
| 1. Public Land Survey   | T 5S R 19W | K-5 |
|                         | T R        |     |
|                         | T R        |     |
|                         | T R        |     |
| 2. Property Controlling | S T R      |     |
| in Section              | S T R      |     |
| 3. Miscellaneous        | S T R      |     |
| Property in Sec.        | S T R      |     |

11/01/00 111#5437 A44  
CORNER \$9.00  
11/01/00 111#5437 A44  
STATE REMON. FEE \$2.00  
Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat  
5. Private Claims

I, Charles W. Barger, in a field survey on September 29 2000  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

Feb 1830  
L. Lyons

Set Frost Corner to Secs 11, 12, 13 & 14  
Beech 13 S42E 10  
Do S86 1/2W 25

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

August 2000

Found 1/2" Iron in Monument Box  
PK in PP S38d08'W 42.73'  
Hydt N44d15'W 47.96'  
Set PK in PP N75d02'E 110.71'  
Set PK in PP S70d20'E 108.0'

SURVEY &  
REMONUMENTATION


JAN 31 2001

SECTION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-5 1" Pipe 36" Long with 2 1/2" Remonumentation Brass Cap in Monument Box  
Witness Tag in PP S38d08'W 42.73'  
Hydt N44d15'W 47.96'  
Witness Tag in PP N75d02'E 110.71'  
Witness Tag in PP S70d20'E 108.0'

AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION  
OF THE ORIGINAL CORNER.



Signed by Charles W. Barger P.S.

Date OCTOBER 26, 2000

Surveyor's Michigan License No. 31589

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983

**2000 Berrien County Remonumentation  
Barger Engineering, Inc.**

**SOUTHEAST CORNER SECTION 11, T5S, R19W  
SOUTHWEST CORNER SECTION 12, T5S, R19W  
K5**

Feb. 1830                      Set Frost Corner to Secs 11, 12, 13 & 14  
L. Lyons                      Beech 13 S42E 10  
Do 8 S86 1/2W 25

Feb. 1876                      Stone w/3 small stones about it  
T. Love                      Syc 3" N74E 4

1954 and 1960                  Monument Box - Stone  
Berrien Co. Rd Comm        Pear NE 38.1'  
Pear SE 41.2'  
6" Walnut NW 33.5'  
Cherry SW 35.4'

Aug 1976                      Survey  
M. Rushlow                   Found 1/4" Iron Pipe in Monument Box  
PP S45W 42.4'  
PP N60W 71.25'  
Hydt N30W 48.1'

Jun 1986                      Survey  
J. Kamer                      Found Iron Pipe in Monument Box  
Hydt N50W 47.7'  
Top of Wood Post S45E 35.45'  
PP S45W 42.45'

Aug 2000                      Found 1/2" Iron in Monument Box  
C. Barger                      PK in PP S38d08'W 42.73'  
Hydt N44d15'W 47.96'  
Set PK in PP N75d02'E 110.71'  
Set PK in PP S70d20'E 108.0'

Barger Engineering, Inc.  
20249.05

**SURVEY &  
REMONUMENTATION**

**JAN 31 2001**

**SECTION**