

1993

BRANCH COUNTY REMONUMENTATION CORNER

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
BRANCH

(County)

Located In:

Corner Code ##

1. Public Land Survey

T 6S R 6W

J-1

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

255

Register of Deeds Stamp & File Number

REGISTER OF DEEDS
John J. Pearson

93 DEC 27 AM 10:07

REC'D FOR RECORD
STATE OF MICHIGAN
BRANCH COUNTY

I, Edward W. Reed in a field survey on December 2, 1993 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

NORTH QUARTER CORNER SECTION 2, T6S, R6W, COLDWATER TWP.

All evidence of any previous survey now destroyed due to the construction of I-69 highway and a new highway overpass bridge.

I-69 highway construction plans.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Using the construction plans of the MSHD plans for I-69, I reset the north quarter corner in accordance with the dimensions stated on said plans and on a straight line with the northeast and northwest section corners of section 2.

Set ½" x 18" rebar iron with ID cap in CI-monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Rebar iron as noted above.

Due west 2.5', East edge of overpass bridge.

Due west 52.0', C/L of north bound lane of I-69

S 43 E 27.1', NE corner of concrete base of concrete guardrail.

N 58 E 25.6', SE corner of concrete base of concrete guardrail.

And is accepted as a careful and faithful reestablishment of the position of the original corner.

Signed by

Edward W. Reed

Date

December 2, 1993

Surveyor's Michigan License No.

33985

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

