SURVEY & REMONUMENTATION

FEB 0 2 1998

REMONUMENTATION

SECTION 12, DUPLAIN TOWNSHIP

SECTION

Surveyor's Michigan License No.

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

004 PAGE 210 LIDER

For corners in Clinton Located In: Corner Code #					RECORDED						
1.	(County) Public Land Survey	T 8N R 1W T R	M4				9 1		and the second		
	Property Controlling S_in Section S_Miscellaneous S_Property in Sec. S_	Section S T R Scellaneous S T R									
4. 5.	Lot No, Records	ed Plat		₁ A	В	C D	E F (э н	ı J þ	ĊĹ	
I,	Wendy A. Papineau	, in a field su	ırveyon June 1997	2	6	5	4	3:	2	1	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land					9	10	11	12			
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as				6	18	17	16	15	14	13	
·	ressed below:			8	19	20	21	22	23	24	
NO	TE: Not more than 2 corner on this certificate.	s, all in the same town	and range, may be recorded	9	30	29	28	27	26	25	
Α.	Description of original mor	nument and accessories	and/or subsequent restoration:	11 - 12	31	32	33	34	35	36	
<u>H-4</u>	Standard East 1/4 Co	rner Section 12, T8N	-R1W	13 L			<u> </u>				
	Wood post placed by Robert Clark Jr, D.S. Jan.26, 1831 S 61 W 31 lks (20.46') 14" Elm N 55 W 29 lks (19.14') 11" Elm Co. Survey by Charles Eddy, C.S. April 14, 1901 Co. Survey Vol II P. 88										
	Stone - No Witness	r, June 1990, Record	ed L. 4, P. 905, S.C.R.								
В.	Description of corner evide	ence found and/or meth	od applied in restoring or reestabli	shina corne	·Γ:						
M-4	Standard East 1/4 Corner Section 12, TBN-R1W										
	Calculated a position on the Michigan Meridian, (between Standard Section Corners, Section 12) at a prorated distance from the C. Eddy survey measurement between the S 1/4 Corner, Section 12 the centerline of the Conrail Railroad. Excavated a 2.5'x3.0'x3.0' deep hole. Found a wood fee post lying horizontally East to West at a depth of 1.8'. Found no evidence of record stone. Intersected the wood post with a line between the Standard Section Corners.										
	There appears to be restablishment of the		nce and this position is acceptional corner.	pted as a	caref	ul an	d fait	hful.		ξ. ή ή	
	Approved by the joint Clinton/Shiawassee County Remonumentation Peer Review Group August 13, 19										
C.	Description of monument f	or corner and accessori	es established to perpetuate locat	ing the pos	ition (of the	corner:				
<u>M-4</u>	Standard East 1/4 Corner Section 12, T8N-R1W										
	Placed a Clinton County Monument, 2"x30" steel pipe, 3 1/4" brass cap and plastic base with a min a monument box							agnet	energy.	45.	
			APPROVED BY CLINTON COUNTY PEER DATED <u>3/13/19</u> 7				1	WE A PAI	NDY PINEAL	To the second	