## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION For corners in

1 01 00111010 111		
Crawford (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>28N</u> R <u>1W</u> T R T R T R	D-10
2. Property Controlling in Section	STR STR	
3. Miscellaneous Property in Sec.	S T R S T R	
4. Lot No, Re	ecorded Plat	

I, Marvin E. Myers , in a field survey on Nov 27, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent

restoration:

Not Set by GLO

Old Map (Purported to be Houghton) (Late 1800's to Early 1900's)

Mon - not given
Wit: None Given

C.E. Ostling No Date Mon - Fd. Conc. Mon. Wit: ½"x18" iron bar N88°46'20"E 40.0 ½"x18" iron bar

S01°14'E 500.0

Farnham, Wirries, & Berning Date unknown Mon – Not Given LCRC L. 2, P. 181 June 16, 1978

N. Parker, P.S. #16939

Mon - Fd. Conc. Mon. used by Ostling

BT 10" J. Pine S35°W 20.2

BT 4" J. Plne S40°E 39.0 BT 8" J. Pine N58°E 45.4

L 182, P. 295 Sept 27, 1979

N. Parker, P.S. #16939 Mon – Fd. Conc. Mon. BT 10" J. Pine S35°W 20.2 BT 4" J. Pine S40°E 39.0 BT 8" J. Pine N58°E 45.4

Oct 6, 1990
M.E. Myers, P.S. 31600
Mon - Fd. Concrete Mon.
of record 16.81 South
& 0.26 East of intersection

of  $\frac{1}{4}$  lines.

3 PAGE 3.38


STATE OF NICHIGAN CRAWFORD COUNTY RECORDED

29 DEC 98 9:48 A.M.

SANDRA HOORE REGISTER OF DEEDS

. :

Register of Deeds Stamp & File Number



L. 463, P. 423

Aug 14, 1998 R.C. Brand, P.S. #43045 Mon - Fd. Conc. Mon. of record 16.81 South & 0.26 East Concrete monument was erroneously placed midway on N-S 1/4 line.

Marvin E. Myers, P.S.

Marvin E. Myers, P. County Surveyor

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found concrete monument16.81 South & 0.26 East of intersection of ¼ lines. Found nothing at the intersection of ¼ lines; found 10" J. Pine S35°W 20.2; found 4" J. Pine S40°E 39.0 0; found 8" J. Pine N58°E 45.4 all being accessories to the concrete monument. Houghton apparently set the concrete monument by single proportion measurement on the N-S ¼, which is an incorrect method of establishing the Center of Section. The Crawford County Peer Group rejected the concrete monument position and the correct position established at the intersection of the N-S ¼ line and E-W ¼ line position was accepted as a careful and faithful establishment of the position of the Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon – Set Standard Crawford County Monument at the intersection of 1/4 lines.

Wit: Concrete monument 16.81 South & 0.26 East of 1/4 line intersection.

Set Carsonite Post East 2.0±

Set nail & tag S. side 10" Jack Pine S82°E 43.76
Found spike in W. side 12" J. Pine S20°W 35.90
Set nail & tag in N. side 6" J. Pine N74°W 19.34

Set nail & tag in NW side 12" J. Pine N37°E 54.86

Signed by MABVING MYEHS
Surveyor's Edit higher of the Surveyor No. 31600 Signed by MABVING SURVEY SU

Date December 23, 1998

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14,1976

REVISED JAN., 1983