### SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	rning Kequireme	at Ol Act 14, Mich. F.A. 191	CRAWFORD COUNTY
Crawford	Located in:	Corner Code #	RECORDED
(County)			13 DEC 99 9:48 A.M.
1. Public Land Survey	T <u>28N R 4W</u> T R T R T R	G-9	SANDRA HOURE REGISTER OF DEEDS
2. Property Controlling S in Section S S S Property in Sec. S	T R T R T R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R R T R		Register of Deeds Stamp & File Number
4. Lot No, Recorded Pla 5. Private Claims	t	•	1 A B C D E F G H I J K L M 2 - 6 - 5 - 4 - 3 - 2 - 1 - 3
I, Marvin E. Myers, in a field survey on	ts mentioned in lines 1 and 2 n the current manual of surve Management or by a decree above were in conformance w	2 above were in conformance with ay instructions of the United States of a Court of Law and for that the with the rules of the Michigan Board	4 7 8 9 10 11 12 12 15 6 18 17 16 15 14 13 17 8 19 20 21 22 23 24 9

#### Description of original monument and accessories and/or subsequent restoration:

Not more than 2 corners, all in the same town and range, may be recorded

P147 Co. Survey Jun 26 1932 Ed Houghton #1122 P20 Co. Survey records July 31, 1933 H.L. Botsford #1647 G.LO - 1856 W. Warner, DS Mon - Old gr. Sec. Cor. Reestablished Mon - Set CT Post for corner Mon - Found Conc & Tile Mon and 2 NBT's Wit: 20" Beech N47°W 51 lks. Wit: none given 18" Beech S10°W 52 lks. LCRC L1, P71 May 5, 1972 K. Ostling # 10068 L. 135 P119 April 11, 1974 G D Henning #2240 Mon - Fd. Conc. filled tile in center of N-S road previously established by Houghton L1, P83 Sept 1971 N. Parker #16939 Mon - Found Conc. Mon Mon - Conc. Mon in Road left in place Wit: Elm clump N51°E 37.4

Wit: 10" Elm N51°E 37.25 Wit: 10" Elm N43E 46.1 10" Maple S42°E 42.3 10" H. Maple N78°W 70.00 12" Maple N 76°W 70.05 10" Maple S50°E 42.1 5/8" Bar West 33.00

L273, P505 1987 C | Robinson #16390 LCRC L2, P243 June 26, 1981 G.F. DeLamater #13030 Mon -- Conc, Tile Monument

Mon - Found 5/8" Rebar Wit: 10" Elm N51°E 37,25 Wit: 6" Maple N83°W 53.60 10" H. Maple N78°W 70.00 6" Maple N38°E 54.61

CRAWFORD COUNTY PEER GROUP APPROVAL

Marvin E. Myers, P.S.

# County Surveyor Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Concrete filled Tile Monument with 5/8" iron core; found 10" (now 16") Maple S42°E 42.3; found 14" (now 16") Maple S60°E 42.56; found 12" (now 16") Maple N76°W 70.05; found 1/2" bar and cap #2240 West 33.00; found Mag nail in SE side Utility Pole S47°W 56.12 Accepted Clay tile monument as the best available evidence of the position of the Original Corner. Replaced Clay tile monument with Standard County Monument.

## Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon - Standard County Monument

14" Maple S60°E 42.56

NOTE:

on this certificate.

Spike in North side above existing grown over nail in 16" Maple S42°E 42.27 Spike in North side above existing grown over nail in 16" Maple N76°W 70.05 Crawford County Nail & tag in South side 10" Maple N63°E 38.32 Carsonite Post East 18.2

Signed by Surveyor's Michigan License No. 31600

TE OF MICHIGANIA SATE OF MICHIGAN MARVIN E. **MYERS PROFESSIONAL** SURVEYOR Date <u>12-03</u> No. 31600 S

OFESSIONALITY
FORM APPROVED BY MICHIGAN STATE BOARD OF PROVIDENCE MANAGEMENT OF PROVIDENCE OF PROVIDENCE

RVEYORS, JAN. 28, 1976 REVISED MAY 14, 1975 REVISED JAN., 1983 YORS

REVISED OCT., 1995