

SURVEY & REMONUMENTATION

JAN 26 1998

STATE OF MICHIGAN
COUNTY OF CHARLEVOIX
RECEIVED FOR RECORD

97 DEC 15 PM 2:43

Charles M. Probert
REGISTER OF DEEDS

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Charlevoix
(County)

Located in:

Corner Code #

1. Public Land Survey

T32N R 7W

MC N. OF LAKE
BTWN. A6-A7

T32N R 8W

MC N. OF LAKE
BTWN. M6-M7

T R

T R

T R

T R

T R

2. Property Controlling
in Section
3. Miscellaneous
Property in Sec.

S

S

S

S

T

T

T

T

R

R

R

R

R

R

R

R

R

R

R

R

R

R

R

R

#18

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Wayne E. Boss May 97

I, _____, in a field survey on _____, 19____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

MEANDER CORNER SOUTH OF EAST QUARTER CORNER SECTION 18 ON NORTH SIDE OF LAKE
OCTOBER 1856
E.D. ATWATER, DEPUTY SURVEYOR
SET IRONWOOD 4 INCH
1. W. ASH 11 INCH N31W 25 LKS.
2. B. ASH 11 INCH N43E 19 LKS.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

MEANDER CORNER SOUTH OF A-6 AT NORTH SIDE OF LAKE

NO EVIDENCE OF ORIGINAL CORNER FOUND OR WITNESSES
REESTABLISHED POSITION ON LINE BETWEEN CORNERS A-6 AND A-7 USING GLO CHAINAGE
OF 23.54 CHAINS (1553.64') SOUTH OF EAST QUARTER CORNER.
Charlevoix Co. Surveyor
APPROVED
Signature Wayne E. Boss
Date: 12-23-97

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

MEANDER CORNER SOUTH OF A-6 AT NORTH SIDE OF LAKE

PLACED STEEL CHARLEVOIX COUNTY MARKER
20" COTTONWOOD S57W 33.75' SET NAIL & TAG
8" W. CEDAR N75E 13.30' SET NAIL & TAG
10" CHERRY N52E 26.70' SET NAIL & TAG
1/2" IR N05W 22.92' CAP 25835, 24595
EDGE OF WATER SOUTH 38' +/-
AND IS ACCEPTED AS A CAREFUL & FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL
CORNER

Signed by _____
Surveyor's Michigan License No. 20703

Date 12/12/97

