أتحسم وسييوا

STATE OF MICHIGAR COUNTY OF CHARLEVOIX RECEIVED FOR ANYTH LAND CORNER RECORDATION CERTIFICATE 96 DEC 11 PH 3: 05

	Filing Require	ement of Act 74, Mich. I		
or corners in Charlevoix	Located In:	Corner Code ##	REGISTER OF DEEDS	
Public Land Survey	7 32N B 7W 7 133N B 7W	M.C. BETWN.  LL& H-1  M.C. BETWN.		SURVEY & REMONUMENTATION
Property Controlling In Section Miscellaneous Property in Sec.	S T R S T R	I-13 & H-13	Ofher # 16 Register of Deeds	FEB 1 9 1998 Stamp & File Number
Lot No	Recorded Plat		A B C b	SECTION
	, in a liefd survey onNO	VEMBER 8 . 19 96	4 7 3-	

hereby certify that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned lines 1 and 2 above were in conformance with regulations and rules therefore as required in the reant manuar of survey instructions of the United States Department of the Interior, great Land angement or by a decrete of a Gourd of Law and/or that the corner points mentioned in lines 3, 4 and 5 over were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a curt of Law, established, re-established, monumented, re-monumented, recovered, found as oreseed below:

(,)

ITE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

M.C. BETWEEN I-I & H-I GLO JUNE 1839 JOHN HODGSON EAST MARGIN OF A LAKE A CEDAR 14 IN DIAMETER FOR MEANDER POST

NO OTHER CORNER RECORD OR CORNER LOCATION FOUND.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M.C. NO EVIDENCE FOUND. CORNER LOCATION ESTABLISHED AT GLO DISTANCE OF 1617 FT. BY PROJECTING THE NORTH LINE OF SECTION 2 WEST TO THE LAKE. DISTANCE FELL ON TOP OF BANK WHICH IS WHERE THE MEADNER CORNER MOST PROBABLY WOULD HAVE BEEN SET.

> Charleveix Co. Surveyor APPROVED Signature\_Mary.C. Ferrett Date: Not 13,1996

Description of monument for corner and accessories established to perpetuate locating the position of the corner. M.C. BETWEEN I-1 & H-1 T32N-R7W COMMON TO M.C. BETWEEN I-13 AND H-13 T33N-R7W CHARLEVOIX CO. MON, SET

I. S.E. COR, MAIN PART OF HOUSE N40W 65.20' 2. 12" CEDAR N20W 36.16' SPIKE & TAG SET PROFESSIONAL SURVEYOR 3. 10" CEDAR N75E 7.65' SPIKE 7 TAG SET 4. TWIN 5" CEDAR S20E 19.76" SPIKE & TAG SET 5. C/L DRIVE NORTH 22" No. 20703 6. WEST TO WATERS EDGE 153.
AND IS ACCEPTED AS A CAREFUL AND FAITHFUL REESTABLISHMENT OF THE POSITION CHAPTER SIGNAL ed by LIBER PROVED BY MICHIGAN STALE BRAND OF LAND SURVEYORS, JAN. 28, 1871 Revised Mar 14, 1975 Revised Jan., 1983

ĵ