

SURVEY &
REMONUMENTATION

MAY 16 1995

COMMISSION

CHEBOYGAN COUNTY REMONUMENTATION CORNER
LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

DEC 29 1994

For corners in
CHEBOYGAN
(County)

Located In:

Corner Code ##

- | | | |
|-------------------------|------------|----------------|
| 1. Public Land Survey | T 36N R 1W | Meander Corner |
| | T R | Sec. 19 |
| | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling | S T R | |
| in Section | S T R | |
| 3. Miscellaneous | S T R | |
| Property in Sec. | S T R | |

RECEIVED FOR RECORD

at 12:40 O'Clock

James Gray

CLERK/REGISTER
CHEBOYGAN COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Richard C. Dunn, in a field survey on October, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. John Mullett 1840
Set wood post
33.10 Chains
North of 1/4 corner
10" B. Ash N62½°E 20 Links

Ron Bischer #22428, 4-23-91
Fnd. 1" Pipe
12" Twin Birch N86°E 27.55'
4" Cedar S22°W 27.8'
6" Balsam S16°E 20.75'

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Meander Corner Section 19. Found 1" Iron Pipe at Cedar Post per Ron Bischer survey dated 4/23/91.

Morris O. Ross

DEC 27 1994

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Meander Corner Section 19. Fnd. 1" Pipe at Cedar Post per Ron Bischer survey dated 4/23/91 and replaced with 5/8" x 3" Iron Bar and 3" aluminum cap and is accepted as a careful and faithful reestablishment of the position of the original corner.

6" W. Pine N65°E 9.77'
9" Cedar S40°E 16.52'
6" Balsam S16°E 21.06'
6" Cedar S40°W 25.70'
Mullett Lake North 28.0'

LIBER 010 PAGE 88

Signed by *Richard C. Dunn* Date December 15, 1994

Surveyor's Michigan License No. 12020

