STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

De	eltaCOUNTY
τ	37.N R 24.W
<u>6</u>	
DESCRIPTION OF CORNER 1/4 corner for sections 7	
CORNER MONUMENTl" iron pipe with 4" aluminum cap	
DATE MONUMENT PLACED AND WITNESSED 6/19/69, F. J. Bray	
WITNESSES TO CORNER 6" Cedar (1/4 S) (NBT) N 78° E, 141	2 links
7" Tamarack (1/4 S) (NBT) S 21° W,	243 links
AND	
CIRCLE CORNER REGISTERED	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two original BT's. Rotted Tamarack stump with overgrowth of lower face (N 59° E 23 links.) Down tamarack with notch and overgrowth on lower face and overgrowth on upper face (S 19° W 11 links). Rotted stake down.

SURVEYOR'S SEAL

SIGNED

GNED REGISTERED LAND SURVEYOR

DATE _

6/26/69

DISTRIBUTION:

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing