SEP 1 3 1994

COMMISSION

Approved By Delta County Land Survey Remonumentation Peer Group Upder Act 345 Of

_, 199*5*/ OT 1990 On-

Chairman

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

FO	r corners in DELTA	Located In:	Corner Code ##			٧.						
	(County)	Located III.	Comer Code			•	-					
1.	Public Land Survey	T <u>39 N</u> R <u>24 W</u> T R T R T R	<u>I-5 8 1-6 </u>	Recorded	1		9 1994	-	Das		 19	
	Property Controlling in Section Miscellaneous Property in Sec.	S T R S T R S T R S T R		9:00 Tuke Duka Cor Regist	មកវរ្វៈ, ខ	fichigar	Stamp					
		Recorded Plat]		A B	C D	E F	G)	н 1 3	j	к	L N
in cu Ma ab Co exp	hereby certify that under reclines 1 and 2 above were in trent manual of survey instrunagement or by a decree of ove were in conformance with until of Law; established, in pressed below:	quirements of P.A. 74, Michigan P.A n conformance with regulations a ructions of the United States Depa a Court of Law and/or that the corn ith the rules of the Michigan Board	A. of 1970, the corner points mention and rules therefore as required in furthernt of the Interior, Bureau of Later points mentioned in lines 3, 4 and of Land Surveyors or by a Decree 6-monumented, recovered, found	ned 6 the 7 d 5 8 of a	3 — 18- 7 — 30- 3 — 30-		9	15	5	—11- —14- —23- —26-		-12 -13 -24 -25
Α.	on this certificate. Description of original I-5 [NW COR S.14] GEORGE	monument and accessories ar ADAIR, D.S 1852 - WOOD POST		12 13 (SPRUCE 10	31-31-	*W-57 I	JINKS)] 34		35_ E" -	- NO	-36
	I-6 [W1/4 COR S.14] GEORG	GE ADAIR, D.S 1852 -WOOD POS	T (Y.BIRCH 16"-N20°W-32 LINKS)	(CEDAR 10'	-S20°	E-20 L	(NKS)					

- M.DAVIS.RLS 1974 FOUND IRON BOLT IN PLACE IDENTIFIED FROM LINES OF OCCUPATION NO EVIDENCE OF "GLO BT'S" REPLACED IRON BOLT W/A 4" X 4" X 36" CONC MON. W/A BRASS CAP STAMPED TO 1D THE CORNER POSITION & REC'D. SAME IN LIBER 2 OF LCR'S ON PAGE 76.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: I-5 [NW COR S.14] FOUND IN PLACE, AT PI OF COUNTY ROAD C/L N & W A 3/4" IRON PIPE SET IN THE REMAINS OF A WOOD POST. DISTANCES TO ADJOINING CORNERS CK WELL WITH "GLO" AND OTHER REC'D. DISTANCES, ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER.

D.A.BROTHERTON - 1896 - IDENTIFIED FROM ORIGINALS - NO NEW WIT'S NOTED - SET IRON STAKE

I-6 [W1/4 COR S.14] FOUND IN PLACE THIS DATE A CONC MONUMENT W/A BRASS CAP STANPED TO ID THE CORNER POSITION. IDENTIFIED THE SAME AS BEING THE MONUMENT I SET IN 1974 FROM THE REMAINS OF BOTH BT'S AS ESTABLISHED IN 1974. ACCEPTED EXISTING MONUMENT AS BEING A CAREFUL & FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: I-5 SET OVER EXISTING MONUNENT A BERNTSEN AINB30 ALUMN MON WITH THE CAP STAMPED TO ID THE CORNER POSITION. SURVEY MONUMENT SIGN POST CEDAR 11" POWER POLE TAMARACK 12"

N87°W N65°E S25°E N30°E 26.10' (TO FACE) 28.70' (TO FACE) 106.44 76.65

I-6 EXISTING 4" X 4" X 36" CONC MONUMENT W/A BRASS CAP STAMPED TO ID THE CORNER POSITION.

SURVEY MONUMENT SIGN POST ELM 6" ASH 12" ELM 4" LARGE FIELD STONE N60°W N45°E N85°E S58'E SOUTH 2.57' (TO FACE) 54.54' 48.381 2.52' (TO FACE) 38, 201

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC & DISTANCES ARE TO A MAIL W/A REFERENCE TAG IN THE OBJECT, UNLESS OTHERWISE NOTED.

Signed by 16926 Surveyor's Michigan License No. ___ FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971