

FEB 18 1994

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Approved By Delta County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On Jan. 50, 1994
Robert B. Schumaker
Acting Chairman

For corners in

DELTA

(County)

Located In:

Corner Code ##

1. Public Land Survey

T 40 NR 23 W

B-5 & B-9

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

B-5 [N1/4 COR SEC 18] B-9 [N1/4 COR SEC 30]

I, M.P. DAVIS, in a field survey on JULY, 19 93,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

B-5 [N1/4 COR SEC 18] WOOD POST - A. MERRYWEATHER, D.S. - 1846 (BURNT TAMERAC 8"-WEST-50 LINKS) (SPRUCE 8"-S59'E-58 LINKS)
M.S. McNABB - 1913 - NO ORIGINALS FOUND - ESTABLISHED PROPORTIONATE DISTANCE BETWEEN CORNERS SET STAKE SCRIBED "1/4"
BT STAKES NE & SW 33'
M.S. McNABB - 1936 - ID STAKE FROM PREVIOUS SURVEY - SET IRON PIPE (BT STAKE NORTH 25')

B-9 [N1/4 COR SEC 30] WOOD POST - A. MERRYWEATHER, D.S. - 1846 (MAPLE-S29'E-5 LINKS) (BEECH-N43'E-17 LINKS)
M.S. McNABB - 1921 - NO ORIGINALS FOUND - ESTABLISHED PROPORTIONATE DISTANCE BETWEEN CORNERS SET IRON BOLT (STUMP 8"-EAST-24')
(FENCE POST- S15'E-5') 1924 SET BT STAKES NW 40' & SE 33'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-5 [N1/4 COR SEC 18] FOUND IN PLACE McNABB'S IRON PIPE 24" BELOW COUNTY ROAD SURFACE, ID CORNER
POSITION FROM EXISTING OCCUPATION & COMPARISON OF McNABB'S MEASUREMENTS TO ADJOINING CORNERS
ACCEPTED THIS MONUMENT AS BEING A CAREFUL & FAITHFUL REESTABLISHMENT OF THE POSITION OF THE
ORIGINAL CORNER.

B-9 [N1/4 COR SEC 30] NO EVIDENCE OF McNABB'S IRON BOLT FOUND, RESTORED CORNER POSITION BY RETRACE-
MENT OF McNABB'S SURVEY OF THE LINE COMMON TO SEC'S 19/30.
ACCEPTED THIS POSITION AS BEING A CAREFUL & FAITHFUL REESTABLISHMENT OF THE POSITION OF THE
ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-5 SET, OVER EXISTING MON, A 5/8" X 18" REBAR W/A 3-1/4" ALUMN CAP STAMPED TO ID COR POSITION, RAISED TO RD SURFACE W/A MON BOX
TAMARACK 4" TAMARACK 8" SPRUCE 9" SURVEY SIGN MONUMENT SIGN POST
N65°E S37°W S40°E NORTH
83.78' 47.55' 99.46' 15.89' (TO FACE)

B-9 SET, 6" BELOW ROAD SURFACE, A 5/8" X 18" REBAR W/A 3-1/4" ALUMN CAP STAMPED TO ID THE CORNER POSITION
DRILL HOLE IN FIELD STONE DRILL HOLE IN FIELD STONE WHITE BIRCH 6" SURVEY MONUMENT SIGN POST
N48°E S67°W S81°E SOUTH
41.22' 67.40' 150.70' 25.0' (TO FACE)

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC & DISTANCES ARE TO A NAIL IN THE CENTER OF THE OBJECT UNLESS OTHERWISE NOTED

Signed by M.P. Davis

Date 12/29/93

Surveyor's Michigan License No. 16926

USER

7 PAGE 370

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

