

SURVEY &
REMONUMENTATION
APR 07 1995
COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Dickinson
(County)

Located In:

Corner Code =#

1. Public Land Survey Section 18 T 39N R 28W
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

B-7

REGISTER OF DEEDS
DICKINSON COUNTY
AND MICHIGAN

RECORDED
1994 DEC -9 PM 3:44

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____
1/4 corner 18 and 19

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, John R. Garske, in a field survey on November 7, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1849 - Township subdivision by James H. Mullett, D.S. Original bearing trees: maple 8" - N53°E, 19 links; fir 8" - N45°W, 15 links.

Old Dickinson Co. Rd. Commission R.O.W. map shows corner at sta 43+34.4, 11.9 feet east.

WEPCO diagram of Section 18 indicates iron pipe at 1/4 corner at east edge of pavement, 38 feet north of C&NW R.R.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" pipe at east edge of Co. Rd. 573, a blacktop road. The location of the pipe matches the distance from the centerline of the C&NW R.R. given above. I am accepting the pipe as the corner due to its general use and acceptance and the chain of evidence given for the corner which could be retraced.

ACCEPTED BY THE DICKINSON COUNTY
SURVEY PEER GROUP AS THE OFFICIAL
CORNER UNDER MICHIGAN PUBLIC ACT
345 OF 1990 AT A MEETING HELD ON
1-23-95
R. J. P.
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced existing pipe with Dickinson County aluminum monument and established the following references: Found 16" spike in tel. pole - N54°E, 43.67 feet. Set ref. mon (Dickinson County alum. mon.) S85°E, 40.00 feet; found chiseled X in N.E. anchor bolt at base of R.R. signal - S06°E, 55.03 feet; found chiseled X in N.E. anchor bolt at base of R.R. signal - S52°W, 33.99 feet.

Signed by John R. Garske
Surveyor's Michigan License No. 28410

Date 12/8/94



FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

B-7

Page 113