REMONUMENTATION

APR 07 1995

Or corners in COMMISSION

Dickins

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Fc	or corners in			
	Dickinson (County)	Located In:	Corner Code =##	
1.	,	Section 20T 39N R 28W T R T R	D-9	
	Property Controlling in Section Miscellaneous Property in Sec.		· · · · · · · · · · · · · · · · · · ·	Register of Deeds Stamp & File Number
I, _ do in cu Ma ab Co exp	John R. Garske John R. Garske hereby certify that under lines 1 and 2 above wer rrent manual of survey ir anagement or by a decree ove were in conformance ourt of Law; established pressed below:	Recorded Plat in a field survey on Oct requirements of P.A. 74, Michigan P.A. re in conformance with regulations an instructions of the United States Depart e of a Court of Lawand/or that the corne e with the rules of the Michigan Board of d, re-established, monumented, re-n	tober 25 and 26 , 19 94 of 1970, the corner points mentione d rules therefore as required in the tment of the Interior, Bureau of Lan ar points mentioned in lines 3, 4 and and Surveyors or by a Decree of the nonumented, recovered, found a	2 6 5 4 3 2 1 3 4 7 8 9 10 11 12 5 6 6 18 17 16 15 14 13 6 7 7 5 8 19 20 21 22 23 24 8 9 9 10 10 10 10 10 10 10 10 10 10 10 10 10
A.	on this certificate	ate. nal monument and accessories and	d/or subsequent restoration:	12 31 32 33 34 35 36

- 1849 Township subdivision by James H. Mullett, D.S. Original bearing trees: hemlock 10" S30°W, 07 links; hemlock 14" N60°E, 07 links.
- 1934 Dickinson Co. Rd. Commission E.R. Nelson's notes indicate cedar stake and iron pipe.

Dickinson Co. Rd. Commission R.O.W. Plat shows 1/4 corner at station 43+74.0, 145.5 feet north of centerline.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1 3/4" galvanized pipe protruding 21" above ground on west edge of lawn at residence with FR#3348. Resident claims that pipe has been there as long as he can remember. Position of pipe agrees with station and offset mentioned above. Accepted pipe as corner position because of the chain of evidence found.

ACCEPTED BY THE DICKINSON COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON

COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Drove existing pipe down and set aluminum Dickinson Co. monument consisting of a 3/4" x 36" long aluminum rod with a 2 1/2" diameter aluminum cap inside existing pipe. Established the following references: wood light pole - North, 44.97 feet; 5" maple in clump of 4 - S52°E, 54.16 feet; 6" maple - S12°W, 74.11 feet; 9" maple - N31°W, 9.48 feet; set carsonite witness post - West, 13.0 feet.

Signed by _

Surveyor's Michigan License No. _

Liber 2

28410

Date 12/8/94

No. 28410

JOHN R. GARSKE LAND SURVEYOR

TITE BOARD OF TAND SURVEYORS, JAN. 28, 1971

REVISED JAN., 1983

D-9 P-119