

SURVEY & REMONUMENTATION

APR 07 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Dickinson

(County)

Located In:

Corner Code #

1. Public Land Survey Section 3 T 39N R 28W I-3  
T      R       
T      R       
T      R
2. Property Controlling S      T      R       
in Section S      T      R
3. Miscellaneous S      T      R       
Property in Sec. S      T      R

4. Lot No.           , Recorded Plat
5. Private Claims             
Section corner to 2, 3, 10 & 11

I, John R. Garske, in a field survey on October 10, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE:** Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original survey by James H. Mullet, D.S., in August 1849. Set post. Original bearing trees: birch 24" - S48°E, 25 links; hemlock 12" - N47°W, 31 links.

1912 - M. Bacco, Dickinson Co. Rd. Commission, didn't find post or B.T.s.

1938 - W.C. Johnson notes he re-established S.W. corner, Section 2. He doesn't say what he set.

1981 - Neal Sperhake, RLS, Champion Timberlands, Forestry Control Map indicates pipe at section corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found a 2" iron pipe on a N-S fence line on the east side of a grassy road. A 9" hemlock is blazed facing the pipe at N25°E, 14 feet and a 8" cedar is blazed facing the pipe at S30°E, 20 feet. The iron pipe checks well with GLO natural feature ties. I am accepting the iron pipe as being in the most probable location of the original corner.

ACCEPTED BY THE DICKINSON COUNTY  
SURVEY PEER GROUP AS THE OFFICIAL  
CORNER UNDER MICHIGAN PUBLIC ACT  
345 OF 1990 AT A MEETING HELD ON  
1-23-95  
RJP  
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced iron pipe with Dickinson County aluminum monument. Established following references: carsonite rail - North, 1.00 feet; 9" hemlock - N25°E, 13.75 feet; 5" cedar - N88°E, 7.24 feet; 8" cedar - S37°E, 19.14 feet; 5" balsam - S29°W, 10.11 feet; west 40.0 feet to centerline trail.

Signed by

John R. Garske

Date

12/8/94

Surveyor's Michigan License No.

28410

