

DEC 18 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

1995 NOV 21 AM 11:25

For corners in
Dickinson

(County)

Located In:

Corner Code #

1. Public Land Survey T 39N R 29W
T R
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Section S T R

A-2

B-1

RECORDED DEEDS
BOOK 11-20-95
PAGE 301

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Robert F. Perkins, in a field survey on Oct. 10, 1995
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-2 West $\frac{1}{4}$ Corner, Section 6
Post by J. Mullett, D.S. 1847
Original Bearing Trees
S.Pine 6" N33°W 5 Lks.
S.Pine 4" S 9°W 9 Lks.

B-1 North $\frac{1}{4}$ Corner, Section 6
Post by J. Mullett, D.S. 1847
Original Bearing Trees
Maple 4" N59°E 30 Lks.
Birch 10" N 8°W 21 Lks.

ACCEPTED BY THE DICKINSON COUNTY
SURVEY PEER GROUP AS THE OFFICIAL
CORNER UNDER MICHIGAN PUBLIC ACT
345 OF 1990 AT A MEETING HELD ON

11-20-95

R.F.P.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: COUNTY REPRESENTATIVE

A-2 No Evidence of Original Corner
or Accessories Found.
Found City of Norway Concrete
Monument buried 8" in Road L.
Appears on Sheet 1-F, City of
Norway Land Record.

Corner Researched in 1994.

B-1 No Evidence of Original Corner
or Accessories Found.
Found 2 $\frac{1}{2}$ " Iron Pipe in E-W Fence and
1 Bearing Tree- Oak 8" N70°W 45' (Dead).
Per Sheet 3-D, City of Noway Land Corner
Record.

Corner Researched in 1994.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-2 Placed Monument Box over Existing
Monument.
S.E. Corner House (Fornetti),
N41°W (M.B.) 130.30'.
N.W. Corner House (Hart),
S66°E (M.B.) 168.60'
Concrete Monument N85°W (M.B.) 33.00'
Concrete Monument S85°E (M.B.) 33.00'
Carsonite Marker S85°E (M.B.) 32.3'

B-1 Replaced Existing Pipe with 2 $\frac{1}{2}$ " Stamped
Remon. Monument.
R.Maple 18" S71°E (M.B.) 22.55'
Ironwood 5" S17°E (M.B.) 50.00'
R.Maple 8" S51°W (M.B.) 12.10'
Oak 14" N89°W (M.B.) 34.70'
Carsonite Marker South 1.0'
Bearing Trees have Duplex Nail at Base.

Signed by

Robert F. Perkins

Date

Nov. 7, 1995

Surveyor's Michigan License No.

12027

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 2, 1991

REVISED MAY 14, 1995

No. 12027

